

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Company
MS
FIRSTCAPITAL INSURANCE
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
WEE
HUNG JING
(HUANG HONGJING)
236A SERANGOON AVENUE 2
#11-149
SINGAPORE 551236

Document no.
Document date 28-12-2020
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2020035991/ 1
Job order date 28-12-2020
Service Advisor TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SMM4033G	BQ14HZH0	27-06-2019	WWWZZZAUZKW022383	Golf Highline 1.4 I TSI 92kW DSG	11,176

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00 ✓	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00 ✓	#1	280.00	299.60
5G6807417BQGRU	Cover For Bumper Primed	1	pcs.	1,165.55 de ✓	#1	1,165.55	1,247.14
	REAR BUMPER						
5G6807568S 9B9	Rear Diffuser Satin Black	1	pcs.	315.27 X n	#1	315.27	337.34
5G0807305D	Bumper	1	pcs.	619.61 X n	#1	619.61	662.98
	REINFORCEMENT						
5G6807863C	Attachment Strip	1	pcs.	64.97 ✓	#1	64.97	69.52
	RR CTR BRACKET						
5G6807393A	Guide Piece	1	pcs.	37.46 X n	#1	37.46	40.08
	LHR TAILLIGHT BRACKET						
5G6807393	Guide Piece	1	pcs.	37.46 X n	#1	37.46	40.08
	LHR SIDE BRACKET						
5G0919491D	Sensor Bracket	1	pcs.	12.13 } ✓	#1	12.13	12.98
5G0919491E	Sensor Bracket	1	pcs.	12.13 } ✓	#1	12.13	12.98
5G0919492D	Sensor Bracket	1	pcs.	12.60 } ✓	#1	12.60	13.48
5G0919491D	Sensor Bracket	1	pcs.	12.13 } ✓	#1	12.13	12.98
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	75.94 ✓	#1	75.94	81.26
D 822150A1	Bonding Agent For Plastic	1	pcs.	59.40 ✓	#1	59.40	63.56
5G0945105C	Reflector	1	pcs.	71.19 X n	#1	71.19	76.17
	LHR						
	LABOUR	3	pcs.	840.00	#1 840	2,520.00	2,696.40
	Spray Painting	3	pcs.	800.00	#1 800	2,400.00	2,568.00
	MS FIRST CAPITAL DIRECT SETTLEMENT DOA : 27/12/2020 TP VEH : SHA4247D SURVEY BY :						

Quotation valid till 04-01-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	7,415.84	1%	572.31	8,175.84	8,748.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Paint prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No claim settlement is allowed
- Customer must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Customer

Service Advisor