



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

09/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 30/12/2020

Supplementary repair cost for vehicle no: GBJ1545L NISSAN NV200 1.5 MT 19'

CHASSIS: VSKYBAM20Z0174415

S/n	Qty	Items / Special Nett	U/price	Amount
1	2	Front Support Panel Side Panel <i>Disluted</i>	\$255.00	\$510.00 ✓
2	2	Front Bumper Fog Lamp Housing <i>cancel</i>	\$115.00	\$230.00 ✓

Subtotal :- \$740.00

*Advice by
P/P 09/01/21
H/S*