LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 78 Shenton Way #07-16 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

05 Jan 2021 Attn: Mohd Rizal, Nur Mariah Huibrechts Date:

Preliminary Advice

Vehicle No : SMQ6242K Accident Date : 01/01/2021 : MITSUBISHI ATTRAGE Make Policy No. : 1900247510 Assignment Date : 04/01/2021 **Excess** : S\$0.00 : 5 Date of Inspection : 04/01/2021 Est. Duration of Repair

Inspection At : CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS)

209 PANDAN GARDENS SINGAPORE 609339

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 9,951.56 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 7,721.58 |
| Check Items (Estimated) | :S\$ | 766.92 |
| Total | :S\$ | 8,488.50 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 60,000.00 COE / PARF Rebate 30,433.00 :S\$

Salvage Value :S\$

Margin for Repair 29,567.00 :S\$

Remarks

| Х |) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|---|---|---|
| |) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
| |) | Other comments : |