

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Monday, 1 February 2021 9:56 AM
To: Shiau Chan (LKKAUTO)
Subject: RE: CHINA-PAPER SURVEY SKE 8835Z DONE BY RASUL

Dear Shiau Chan,

AUDIT CHECK DONE FOR SKE8835Z, FOUND DASHBOARD RADIO CONSOLE BOARD & AIR CON DUCT DAMAGED ARE UNLIKELY CONSISTENT .

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Monday, 1 February, 2021 8:52 AM
To: Simon Ho (LKKAUTO)
Subject: CHINA-PAPER SURVEY SKE 8835Z DONE BY RASUL

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)