

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : **FIRST CAPITAL INSURANCE LTD**

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTMG/TP/2012/009
Policy No:	PNMC2020-00001583	Date of Loss:	09/12/2020
Vehicle Reg. No.:	FBF7739B	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SH2656C
Any Injuries?	yes	Contact No:	96300401
Insured/Claimant:	MOHAMMED MOKTAR BIN YUSOFF	Driver:	MUHAMMAD AMZAR BIN MOHAMMED MOKTAR

Make/Model:	Yamaha, T135	Vehicle Reg. Date:	26/11/2011
Vehicle Colour:		Engine Number:	
Chassis No:	5YP303263	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss Side Swipe
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	4,723.20
Miscellaneous Items	435.00
Labour	770.00
Paintwork Labour	350.00
Towing	0.00
Gross Total(S\$):	6,278.20
GST 7.00%(S\$):	439.47
Nett Amount(S\$):	6,717.67

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FENDER	170.00	-10.00	153.00
2	1	FRONT FORK LH	190.00	-10.00	171.00
3	1	FRONT SIDE LAMP LH	230.00	-10.00	207.00
4	1	FRONT SIDE LAMP RH	230.00	-10.00	207.00
5	1	FRONT WHEEL RIM	200.00	-10.00	180.00
6	1	FRONT FAIRING	380.00	-10.00	342.00
7	1	FRONT FAIRING INNER FAIRING	350.00	-10.00	315.00
8	1	FRONT SIDE FAIRING LH	130.00	-10.00	117.00
9	1	FRONT SIDE FAIRING INNER GARNISH LH	65.00	-10.00	58.50
10	1	FRONT HEADLAMP	365.00	-10.00	328.50
11	1	FRONT HEADLAMP FAIRING	290.00	-10.00	261.00
12	1	FRONT HEADLAMP INNER FAIRING	265.00	-10.00	238.50
13	1	FRONT SIDE MIRROR LH	65.00	-10.00	58.50
14	1	FRONT SIDE MIRROR RH	65.00	-10.00	58.50
15	1	FRONT BALANCER LH	12.00	-10.00	10.80
16	1	FRONT BALANCER RH	12.00	-10.00	10.80
17	1	FRONT CLUTCH LEVER LH	25.00	-10.00	22.50
18	1	FRONT BRAKE LEVER RH	25.00	-10.00	22.50
19	1	FRONT SPEEDOMETER	480.00	-10.00	432.00
20	1	CENTRE FAIRING	155.00	-10.00	139.50
21	1	CENTRE SIDE FAIRING LH	105.00	-10.00	94.50
22	1	FRONT FOOT GEAR LEVER LH	85.00	-10.00	76.50
23	1	FRONT FOOT REST LH	45.00	-10.00	40.50
24	1	FRONT FOOT REST BRACKET LH	165.00	-10.00	148.50
25	1	ENGINE CRANK CASE COVER LH	177.00	-10.00	159.30
26	1	ENGINE CRANK CASE COVER GASKET	25.00	-10.00	22.50
27	1	REAR FOOT REST LH	45.00	-10.00	40.50
28	1	REAR FOOT REST BRACKET LH	165.00	-10.00	148.50
29	1	REAR FAIRING LH	330.00	-10.00	297.00
30	1	REAR TAILLAMP	347.00	-10.00	312.30
31	1	FRONT FAIRING LOGO	55.00	-10.00	49.50
			Total Parts (\$\$)		4,723.20

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE	35.00	0.00	35.00
2	1	FRONT FAIRING STICKER	70.00	0.00	70.00
3	1	FRONT SIDE FAIRING STICKER LH	65.00	0.00	65.00
4	1	CENTRE INNER BOX	85.00	0.00	85.00
5	1	ENGINE OIL	75.00	0.00	75.00
6	1	REAR FAIRING STICKER LH	70.00	0.00	70.00
7	1	REAR NUMBER PLATE	35.00	0.00	35.00
			Sub Total (\$\$)		435.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace	40.00	0.00	40.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		Damaged Parts.			
2	1	To Conduct Wheel Balancing	60.00	0.00	60.00
3	1	To Dismantle and Refit Front Undercarriage.	220.00	0.00	220.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	0.00	450.00
Gross Labour Cost (\$\$)					770.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	350.00	0.00	350.00
Gross Labour Cost (\$\$)					350.00

< END OF ESTIMATES >