

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 7 January 2021 5:43 PM
To: sbk5643e@yahoo.com
Cc: SUR
Subject: FBN 3111X / OD / AIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **FBN3111X (Excess \$300/-). On Lump Sum**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

**All Checked and Supplementary items to resurvey with CLEAR photos on damaged portion as per consistency
After paint resurvey to take photos for item to ensure they are replaced. Mentioned items being repaired or reuse,**

**STEERING BRIDGE
LEFT SIDE COVER
SPORT RIM FRONT
FRONT NUMBER PLATE**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)