

8 Kaki Bukit Ave 4 #08-45/46 Premier@ Kaki Bukit S415875  
Tel: 6702 1555 Fax: 6702 1444 ROC No. : 201500047H

**ESTIMATE**

TO	: CN TAIPING	DATE	: 30/12/2020
ATTENTION	: MOTOR CLAIM DEPARTMENT	JOB TYPE	: THIRD PARTY CLAIM
<u>VEHICLE DETAILS</u>		<u>ACCIDENT DETAIL</u>	
VEHICLE NO.	: GBB6126Y	DATE	: 27/12/2020
MAKE / MODEL	: TOYOTA DYNA	TIME	: 15:50
CHASSIS NO.	: JTFAT35Y00-K200836	<i>Xiao Chan</i>	
OWNER INSURANCE	: EQ		
POLICY NO.	: DMCPHQ20-000220		
PERSON INCHARGE	: Yvette   T: 6702 1555   D: 9296 9185   F: 6702 1444   yvette@skauto.com.sg		

CLAIM DETAIL : LIST PRICE (\$S)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Bent</i>	1	\$ 485.00	\$ 485.00 ✓
2	FRONT HEADLIGHT LH/RH <i>Cracked</i>	2	\$ 725.00	\$ <del>1,450.00</del> 1,450.00 ✓
3	FRONT HEADLIGHT LOWER RUBBER LH/RH <i>new</i>	2	\$ 38.00	\$ 76.00 ✓
4	FRONT GRILLE <i>Cracked</i>	1	\$ 550.00	\$ 550.00 ✓
5	FRONT ( LOGO ) <i>new</i>	1	\$ 75.00	\$ 75.00 ✓
6	FRONT ( DYNA ) <i>new</i>	1	\$ 75.00	\$ 75.00 ✓
7	FRONT PANEL <i>Dented</i>	1	\$ 1,150.00	\$ 1,150.00 ✓
8	FRONT PANEL TOP GARNISH <i>cut</i>	1	\$ 310.00	\$ 310.00 ✓
9	FRONT PANEL SIDE GARNISH LH/RH <i>new</i>	2	\$ 130.00	\$ 260.00 +
10	FRONT HINGES <i>new</i>	1	\$ 366.00	\$ 366.00 +
11	FRONT HINGES MOUNTING LH/RH <i>new</i>	2	\$ 773.00	\$ 1,546.00 +
12	FRONT WIPER ARM LH/RH <i>new</i>	2	\$ 120.00	\$ 240.00 +
13	FRONT WIPER MOZZLE LH/RH <i>new</i>	2	\$ 47.00	\$ 94.00 +
14	FRONT WIPER PANEL <i>Rejis</i>	1	\$ 275.00	\$ 275.00 +
15	FRONT WIPER SIDE PANEL RH <i>new</i>	1	\$ 130.00	\$ 130.00 +
16	FRONT SIDE MIRROR PANEL LH <i>new</i>	1	\$ 130.00	\$ 130.00 +
17	FRONT DOOR LH/RH <i>Rejis</i>	2	\$ 1,600.00	\$ 3,200.00 +
18	AIRCON BLOWER MOTOR <i>new</i>	1	\$ 300.00	\$ 300.00 +
19	BRAKE OIL HOSE <i>new cut</i>	3	\$ 113.00	\$ 339.00 ✓
20	HANDBRAKE CABIE <i>new</i>	1	\$ 172.00	\$ 172.00 ✓
21	GEAR CABLE <i>new</i>	1	\$ 715.00	\$ 715.00 ✓
22	REAR TAILLAMP LH/RH <i>Cracked</i>	2	\$ 220.00	\$ 440.00 ✓
23	REAR TAILLAMP BRACKET LH/RH <i>BAF</i>	2	\$ 175.00	\$ 350.00 ✓
24	REAR NUMBER PLATE BRACKET <i>Bent</i>	1	\$ 177.00	\$ 177.00 ✓

TOTAL PRICE : \$ 12,905.00  
LIST LESS 25% : \$ 3,226.25  
SUB TOTAL PRICE : \$ 9,678.75

*5138*  
*3853.50*

CLAIM DETAIL : PARTS S/NETT

S/N	DESCRIPTION	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	FRONT PANEL SEALANT <i>Neu</i>	1	\$ 120.00	\$ 120.00 <i>60</i>
2	FRONT PANEL TOP GARNISH CLIPS SET <i>Neu</i>	1	\$ 30.00	\$ 30.00 <i>20</i>
3	FRONT PANEL SIDE GARNISH CLIPS SET <i>Neu</i>	1	\$ 15.00	\$ 15.00 <i>+</i>
4	FRONT SIDE MIRROR PANEL CLIPS SET <i>Neu</i>	1	\$ 15.00	\$ 15.00 <i>+</i>
5	FRONT GRILLE CLIPS SET <i>Neu</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
6	FRONT NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00 <i>50</i>
7	BRAKE OIL ( DOT 3 ) <i>Neu</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
8	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
9	REAR BUMPER REVERSE SENSOR SET <i>Dangd</i>	1	\$ 280.00	\$ 280.00 <i>20</i>
10	REAR BUMPER REVERSE CAMERA <i>Dangd</i>	1	\$ 380.00	\$ 380.00 <i>350</i>
11	STICKERS ( 70 KM/H ) <i>3me</i>	1	\$ 50.00	\$ 50.00 <i>10</i>
12	STICKERS ( 13 PAX )	1	\$ 50.00	\$ 50.00 <i>10</i>
13	COMPANY STICKERS <i>Hee</i>	1	\$ 200.00	\$ 200.00 <i>120</i>
14	FRONT DOOR COMPANY STICKER SET <i>Neu</i>	1	\$ 180.00	\$ 180.00 <i>60</i>
15	REAR ALUMINIUM END DOOR LH/RH <i>Dented.</i>	2	\$ 3,800.00	\$ <del>2800</del> 7,600.00 <i>2800</i>
16	REAR ALUMINIUM END DOOR LOCK BAR LH/RH <i>Best</i>	2	\$ 600.00	\$ 1,200.00 <i>600</i>
17	REAR ALUMINIUM END DOOR LOCK BAR BRACKET LH/RH <i>Dangd</i>	6	\$ 100.00	\$ 600.00 <i>300</i>
18	REAR ALUMINIUM END DOOR LOCK CATCH LOWER LH/RH <i>Best</i>	2	\$ 150.00	\$ 300.00 <i>20</i>
19	REAR ALUMINIUM END DOOR LOWER PANEL <i>Dented</i>	1	\$ 2,800.00	\$ 2,800.00 <i>500</i>
20	REAR ALUMINIUM END DOOR PILLER <i>Repis</i>	2	\$ 1,800.00	\$ 3,600.00 <i>+</i>
21	REAR FLOOP PANEL TOP BOARD <i>Neu</i>	1	\$ 1,800.00	\$ 1,800.00 <i>+</i>
22	RIVET SET <i>Neu</i>	1	\$ 200.00	\$ 200.00 <i>60</i>

S/N TOTAL PRICE: \$ 19,660.00

5390

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	DESCRIPTION	PRICE	ADJUST
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION REMOVE/REFIT REAR CARGO CARRIER BED	\$ 3,500.00	<i>2000</i>
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,800.00	<i>1500</i>
3	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	<i>x</i>
4	TO APPLY ANTI-RUST & TUFF KOTE	\$ 300.00	<i>120</i>
5	TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	<i>60</i>
6	TO DISMANTLE & REPLACED REAR REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	<i>50</i>
7	TO DISMANTLE & REPLACED REAR REVERSE CAMERA WITH DISTANCE SETTING	\$ 180.00	<i>50</i>
8	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	<i>x</i>

LABOUR TOTAL PRICE: \$ 6,400.00

3880

ESTIMATE REPORT

TOTAL PARTS PRICE : \$	29,338.75
TOTAL LABOUR PRICE : \$	6,400.00
TOTAL AMOUNT : \$	<u>35,738.75</u>

APPROVED DETAILS

NO.OF REPAIR DAYS :  
P & P OR LUMPSUM :  
SURVEYED BY :  
CONTACT NUMBER :  
E-MAIL :

Adnan G  
L/S 31/12/20  
14 Days.

total : 13123.50  
L/S : 10.5K ✓

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: