

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

4-Jan-21

Our ref : TP/4926/21

HockHua Tonic Pte Ltd

TP China
Xiao Tong
VSKYBAM2020157979

RE : estimate cost for vehicle no : GBH 6185U

1 pc	rear lh door <i>Dented</i>	\$	1,469.60	nett ✓
1 pc	NV 200 emblem <i>new</i>		141.70	✓
2 pcs	rear lh door hinges <i>new</i>		230.00	+
1 pc	rear lh door outer handle <i>Dented</i>		352.00	168.50
1 pc	Nissan emblem <i>new</i>		64.90	✓
1 pc	wiper arm <i>new</i>		89.00	+
1 pc	wiper motor <i>Dented</i>		310.80	✓
1 pc	rear lh door top lock <i>new</i>		115.00	+
1 pc	rear lh door lower lock <i>Jammed</i>		115.00	✓
2 pcs	rear no plate lamp <i>new</i>		160.40	+
1 pc	rear lh door trimboard <i>Dented</i>		220.00	193.
10 pcs	rear lh door trimboard clips <i>new</i>		51.00	-20
1 pc	rear lh door rubber <i>cut</i>		168.70	✓
1 pc	rear lh door w/strip <i>new</i>		111.00	+
1 pc	rear rh door <i>Dented</i>		1,102.00	✓
2 pcs	rear rh door hinges <i>new</i>		230.00	+
1 pc	rear rh door rubber <i>cut</i>		106.00	✓
1 pc	rear rh door trimboard <i>new</i>		145.00	+
10 pcs	rear rh door trimboard clips <i>new</i>		51.00	+
1 pc	rear rh door top lock <i>new</i>		115.00	+
1 pc	rear rh door lower lck <i>Jammed</i>		115.00	✓
2 pcs	taillamp <i>cracked</i>		554.00	✓
1 pc	rear bumper <i>Dented</i>		632.70	✓
2 pcs	rear bumper reflector <i>cracked</i>		123.80	✓
2 pcs	rear bumper retainers <i>new</i>		84.00	✓
10 pcs	rear bumper clips <i>new</i>		51.00	-30
1 pc	rear bumper sponge <i>Dented</i>		94.00	✓
1 pc	rear bumper tow hook cover <i>new</i>		21.40	+
1 pc	end panel inner <i>Dented</i>		776.00	✓
1 pc	end panel outer <i>Dented</i>		511.00	✓
1 pc	spare tyre tray <i>Bent</i>		421.00	345
1 pc	spare tyre screw <i>new</i>		21.40	✓
1 pc	exhaust pipe <i>new</i>		552.00	+
1 pc	floorboard panel <i>Rips</i>		1374.60	+
			<u>10680.00</u>	

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : GBH 6185U

Bal brought forward: \$ 10,680.00

1 pc	floorboard panel inner garnish <i>del</i>	175.70 ✓
10 pcs	floorboard panel inner garnish clips <i>new</i>	51.00 20
		10,906.70
	less 10%	1,090.67
		9816.03

1 pc	rear lh door Co logo <i>new</i>	400.00 snett 280
1 pc	70 km/h sticker <i>new</i>	25.00 10
1 pc	6 pax sticker <i>new</i>	25.00 10
1 pc	reverse sensor <i>new</i>	250.00 200
1 pc	rear no plate <i>Best</i>	30.00 ✓
1 pc	camera <i>new</i>	400.00 350
1 pc	rear lh door gum <i>new</i>	50.00 ✓
1 pc	rear rh door gum <i>new</i>	50.00 ✓
	Panel beating.	1,800.00 1200
	Spray painting.	1,500.00 1200
	Wiring.	30.00 ✓
	Remove & refit rh door glass.	100.00 60
	Remove & refit lh door glass.	100.00 60
	Transfer rh door parts.	80.00 60
	Transfer lh door parts.	80.00 60
	Remove & refit exhaust pipe.	80.00 5
		14816.03
	Plus 7% GST	1037.12
		15853.15

SD : Fifteen thousand eight hundred fifty-three & cents fifteen only.

1 pc ply wood
Cml'd

400 SN

200

25 (SN).

total: 10238.16

h/s: 8150.

7042.40
633816

3900

Adrian L
4/5 05/01/21

09 Days.