


ALFRED AUTO

Services & Supplies

Bldg 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
 Email: alfredauto@hotmail.com

Tyre & Sports Rim



Reference No.: 20121

Date: 2.1.2021

Yeo Poh Tin

16 Windsor Park Road

Singapore 574125

Range Rover Velar 2.0S 14R

Estimate Repair Cost for Vehicle Reg. No: SGZ 1200 M

2397-60

1 Pc. Front Bumper <i>monody broken / cut</i>	3,123.00 3 ✓
1 Pc. Front Bumper Side Retainer <i>svz</i>	39.00 X
2 Pcs. Front Bumper Parking Sensor <i>svz</i> @ 312.00	624.00 X
10 Pcs. Front Bumper Clips <i>svz</i> @ 6.00	60.00 30 ✓ SH
1 Pc. Front Fender <i>svz</i>	1,170.00 X
1 Pc. Front Fender Dust Garnish <i>svz</i>	388.00 X
10 Pcs. Front Fender Dust Garnish Clips <i>svz</i> @ 5.50	55.00 X
1 Pc. Front Head Lamp Assy (LH) <i>svz</i>	3,510.00 X

Total (Panels / Parts): **8,969.00 (SGD)**

1pc Front Bumper + H proctor dislodged 121.60 ✓

LABOR CHARGES

To check wiring.	SH 30.00	labor 1080.00	120.00 <i>HH</i>
To repair & renew all accident affected damage area & straightening damage area.			800.00 400/-
To respray painting on all accident damage affected area. (2 color)			900.00 500/-
To rust proof all accident affected area.			150.00 30/-
To diagnostic all accident sensors & erase fault code.			180.00 150/-
To check computer wheel alignment & camber, castor.			180.00 <i>HH</i>

Total (Labor Charges): **2,330.00 (SGD)**

T/P 3629-20
 3 days. ✓

ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 #01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	8,969.00
LABOR CHARGES	2,330.00

Grand Total: **11,299.00 (SGD)**

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

Alfred Quah

ALFRED AUTO SERVICES & SUPPLIES [WITHOUT PREJUDICE SAVE AS TO COSTS]

08/01/2021 @ 0930hrs
H/A Actual

Ryan P.A by P.A.

LKK Auto

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: