



Your Ref : S1M02ZVR

Date: 21<sup>st</sup> May 2021

Our Ref : CS/ASM21000257/Aqd3e2

**M/s AXA Insurance Pte Ltd**  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811  
(The Motor Claims Department)

Attn: Khor Saw Theng

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGC 8295P**  
**INSURED VEHICLE: SJV 2760S**  
**ACCIDENT ON 05/01/2021**

Instruction was received to inspect the vehicle Reg. No. SGC 8295P. The inspection was conducted on 06/01/2021 at the premises of M/s Automobile Hub Enterprise, 1 Kaki Bukit Avenue 6 #02-11 Autobay, Singapore 417883.

The following vehicle information was recorded:

Registration Number	: SGC 8295P
Make/Model	: Toyota Vios 1.5E A
Year of Registration	: 2005
Body Colour	: Red
Chassis Number	: MR053HY4204171128
Engine Capacity	: 1497 cc
Speedometer Reading	: 267918 km

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as “**uneconomical Total Loss**”.

Market Value	S\$ 1,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 258.00)
Nett Liability	S\$ 742.00
	=====

Vehicle Inspected By:



ADRIAN LING WAI PING  
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust),MBA(UK),  
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,  
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),  
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.