

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SM021000261/443

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLN9333P

at Workshop m/s

Ace Automobile

of

Insured:

YQ 6276

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

421k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Rep 7k.

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

B-1 6yrs 4m

we und 30-4-2027 LTA #31714

not 10286

19/1/21 L/s \$6800 confirmed with Anna Cred: 492072.41%

Veh No:

SLN9333P

Yr Regn:

11/7/07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

Honda civic

c.c

1595

Colour

Beige

A/C: Insured / Std / NI / NA

Sp.Reading

228721

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMFD452075200919

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

1/1/21

D.O.I.

7/1/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

12

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	166J
Vehicle Details	
Vehicle No.:	SLN9333P
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2021
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6L VTI 5MT
Primary Colour:	Beige
Manufacturing Year:	2007
Engine No.:	R16A12001653
Chassis No.:	JHMFD45207S200919
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$17,473.00
Original Registration Date:	11 Jul 2007
First Registration Date:	11 Jul 2007
Transfer Count:	0
Actual ARF Paid:	\$19,221.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$50,230.00
COE Rebate Amount:	\$31,714.00
Total Rebate Amount:	\$31,714.00

The information contained herein is correct as at 07 Jan 2021

OK

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

SGCARMART
WARRANTY

BUY A CAR PROTECTED BY SGCARMART USED CAR WARRANTY



Pay \$0 for repairs



188-point check done

VIEW NOW



honda civic

Price Range



Depreciation



> 10 year(s)



Vehicle Type



Home » Used Cars » Car Fleet Automobile » Honda Civic 1.6A VTi (COE till 11/2028)

Honda Civic 1.6A VTi (COE till 11/2028)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$55,800

Depreciation ⓘ \$7,120 /yr

Reg Date

07-Nov-2008

(7yrs 9mths 30days COE left)

Mileage N.A.

Manufactured ⓘ

2008

Road Tax ⓘ \$962 /yr

Transmission

Auto

Dereg Value ⓘ \$23,248 as of today (change)

OMV ⓘ

\$20,211

COE ⓘ \$29,670

ARF ⓘ

\$20,211

Engine Cap 1,595 cc

Power

92.0 kW (123 bhp)

Curb Weight ⓘ 1,220 kg

No. of Owners ⓘ

4

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Honda Civic (2006-2012)

Description

\$0 Down & Full Loan Available. 100% Approval. Car Fr. \$400/mth Only. Bad Credit & Discharged Bankruptcy Accepted. All Cars With Warranty. Loan Amt Stated. We Have Interest Fr. 1.88%. Open Daily Till 11pm Including Sunday & PH. Call/Whatsapp To Set Appt. Online Pre-loan Submissions Available

Category


COE Car

Status

Available

Re:

Compare



Shortlist

Compare

More Actions

Seller Information

Car Fleet Automobile

48 vehicles for sale. 1 sold in pa:

200 Jalan Sultan #02-08

Textile Centre

Tel: 69800655

Search cars nearby



Bobby

Sam

Lynn

Suhana



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 1

Vehicle No. SLN9333P HONDA CIVIC

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BOOTLID <i>3uc ✓</i>		1085.40	✓ 610.70
1	REAR BOOTLID LOCK <i>tw/1m ✓</i>		243.50	✓ 198.60
1	REAR BOOTLID "HONDA" BADGE <i>ner ✓</i>		79.00	✓ 28.80
1	REAR BOOTLID "CIVIC" EMBLEM <i>ner ✓</i>		85.00	✓ 36.50
1	REAR BOOTLID "1.6" EMBLEM <i>ner ✓</i>		65.00	✓ 32.00
1	REAR BOOTLID "i-VTEC" EMBLEM <i>ner ✓</i>		90.00	✓ 35.00
2	REAR BOOTLID HINGE RHS & LHS @\$145.00 <i>2 X</i>		290.00	X
1	REAR BOOTLID WEATHERSTRIP <i>tw/1 ✓</i>		236.00	✓ 97.60
2	REAR BOOTLID STOPPER RHS & LHS @\$75.00 <i>1 X</i>		150.00	X
1	REAR BOOTLID INNER TRIM BOARD <i>1 X</i>		250.00	X
2	REAR BOOTLID LAMP RHS & LHS @\$355.00 <i>202-20X2</i>		710.00	✓ 404.40
1	REAR BOOTLID NUMPER PLATE GARNISH <i>320</i>		211.00	✓ 48.50
2	REAR BOOTLID NUMPER PLATE LAMP LH & RH @\$86.40 <i>1 X</i>		172.80	X
2	REAR TAILLAMP RHS & LHS @\$513.00 <i>280-20</i>		1026.00	✓ 560.40
2	REAR TAILLAMP PANEL LH & RH @\$214.60 <i>1 PC</i>		429.20	✓ 185.20
1	REAR BUMPER <i>325</i>		758.00	✓ 638
2	REAR BUMPER SIDE RETAINER @\$90.30 <i>20X2=40</i>		180.60	✓ 40
1	REAR BUMPER MUD SHIELD <i>1 X</i>		140.00	X
1	REAR END PANEL <i>Body 100</i>		510.00	✓ 296.60
1	REAR END PANEL GARNISH <i>tw/1</i>		145.00	✓
2	REAR FENDER RHS & LHS @\$741.50 <i>1/5 3uc 0/5 1 PC</i>		1483.00	✓ 741.50
2	REAR FENDER INNER BOARD RH & LH @\$394.60 <i>De/turn</i>		789.20	✓ 490
1	REAR CARPLATE LAMP <i>1 X</i>		110.00	X
1	REAR SPARE TYRE PANEL <i>crumpled ✓</i>		1125.00	✓ 911.00
1	REAR SPARE TYRE PANEL TOP BOARD <i>negot ✓</i>		487.50	✓ 316.00
1	EXHAUST SILENCER ASSEMBLY <i>2 X</i>		980.00	X
1	EXHAUST SILENCER ASSEMBLY CENTRE PIPE <i>2 X</i>		395.00	X
1	EXHAUST SILENCER CHROME & PIPE <i>325</i>		400.00	60 S. netf
4	EXHAUST SILENCER MOUNTINGS <i>1 X</i>		210.00	X
1	REAR WINDSCREEN <i>1 X</i>		1110.00	X
1	REAR WINDSCREEN MOULDING <i>ner ✓</i>		71.00	✓
2	REAR WINDSCREEN SIDE GARNISH LH & RH @\$78.30 <i>1 X</i>		156.60	X
2	REAR FENDER INNER PANEL LH & RH @\$857.30 <i>2 X</i>		1714.60	X
			15888.40	
less 20%			3177.68	20%
			12710.72	
SPECIAL NETT ITEMS				
1 SET	REVERSE SENSOR <i>shutb</i>		280.00	200
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>1 X</i>		80.00	X
1 SET	REAR CARPLATE WITH HOLDER <i>1 X</i>		70.00	X
1	REAR SPARE TYRE PANEL SEALANT <i>ner</i>		180.00	100
1	REAR FENDER SEALANT <i>1 X</i>		100.00	X
1 SET	REAR BUMPER CLIPS <i>ner</i>		100.00	30
1	REAR WINDSCREEN SEALANT <i>ner</i>		80.00	40
1	REAR END PANEL SEALANT <i>ner</i>		100.00	50
Total Parts			13700.72	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLN9333P HONDA CIVIC

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1680
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	1200
3	To remove and refix wiring at damaged areas	200.00	30
4	To perform anti rust treatment on affected areas	200.00	120
5	To remove & refix / replace front trims, garnish and fitting so as to facilitate repairs as front compartment	210.00	80
6	To remove rear boot mechanism	180.00	60
7	To remove and replace rear exhaust silencer	210.00	60
8	To remove and refix rear car seat	180.00	Repaired X
9	To remove and replace rear windscreen	120.00	✓
10	To conduct water seepage test	120.00	not X
Labour Total :		4820.00	
TOTAL (PARTS & LABOUR):		18520.72	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authored
Dear
Marius

7/1/21

1/5 \$ 6800

Whn phw After rep
12 days.

7-5886.80
20%

7-4709.44
S.N-480.00

2-3350

5-39.44
20%

6831