

## Shiau Chan (LKKAUTO)

---

**From:** Wai Yin Ng <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 8 January 2021 9:33 AM  
**To:** Shiau Chan (LKKAUTO)  
**Cc:** Claims  
**Subject:** FW: TP VEHICLE SHC 5436H DOA: 04/01/2021 -- AAD2101-013  
**Attachments:** SHC5436 EST.pdf

[Without prejudice](#)

Dear Shiau Chan

Amount confirmed \$1,200 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)  
\* Kindly let us have the discharge voucher within the next 30 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.*

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]  
**Sent:** Thursday, 7 January, 2021 3:08 PM  
**To:** Wai Yin Ng <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHC 5436H DOA: 04/01/2021

Dear Wai Yin,

WITHOUT PREJUDICE

Based on our surveyor marking estimate, the calculation of repair cost will be at Lump Sum \$1,200.00 before GST and 1.5 repair days.

Kindly check.

Best Regards,  
**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)