

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile					
	AIG ASIA PACIFIC	INSURANCE PTE LTD	Ref:	CS3/AIG20009671/Qvf3e2-1	
	78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120		Date:	13/01/2021	
	ATTN : LEE MING	YAO	Code:	AIG	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLR 8803K	Veh. Inspected	SBS 8429X	
	Policy No.	1700052784	Coverage (\$)	0.00	
	Claim No.	2828444162SG	Excess (\$)	0.00	
	Assign From	LEE MING YAO	Assign Date	07/01/2021	
2. Vehicle Particulars & Condition					
	Make & Model	SCANIA KUB4X2	c.c	8867	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	YS2K4X20001862234	Colour	MULTI COLOUR	
	Odometer	1013412 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
	L/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
	R/H Rear Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
	L/H Rear Tyre	275/70 R22.5	BRIDGESTONE	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	06/09/2020	Inspection Date	10/09/2020	
	Survey held at	15 Ang Mo Kio St 63			
	Repairer	SBS TRANSIT LTD (HQ)			
5a.	_				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				