

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:


Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:



Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

we ent. 23-2-2022 LTA # 13536  
NLT # 3464

15/1/21 4/5 \$1200 cont. and wli m127m

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SFY2046C

Date of Accident : 01 January 2021

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Messrs Jeeka

Date : 04 January 2021

Estimate To Repair SKE3158C - Toyota Prius C CVT  
Chassis No : JTDKD3B3801001512

| S/No                              | Quantity | Description                                                                                                             | Amount      |
|-----------------------------------|----------|-------------------------------------------------------------------------------------------------------------------------|-------------|
| <u>LIST ITEMS</u>                 |          |                                                                                                                         |             |
| 01                                | 1 pc     | rear bumper                                                                                                             | \$ 645.00   |
| 02                                | 2 ps     | rear bumper side retainer @ \$66.00                                                                                     | \$ 132.00   |
| 03                                | 1 pc     | rear bumper reinforcement                                                                                               | \$ 396.00   |
| 04                                | 2 ps     | rear bumper reinforcement bracket @ \$98.90                                                                             | \$ 197.80   |
| 05                                | 2 ps     | taillamp @ \$250.00                                                                                                     | \$ 500.00   |
| 06                                | 6 ps     | taillamp clips @ \$4.30                                                                                                 | \$ 25.80    |
| 07                                | 6 ps     | taillamp clip holder @ \$4.30                                                                                           | \$ 25.80    |
| 08                                | 1 pc     | tailgate lid lock                                                                                                       | \$ 374.00   |
| 09                                | 1 pc     | tailgate lid Toyota emblem badge                                                                                        | \$ 39.60    |
| 10                                | 1 pc     | tailgate lid centre logo badge                                                                                          | \$ 47.90    |
| 11                                | 1 pc     | tailgate lid Prius C emblem                                                                                             | \$ 44.00    |
| 12                                | 1 pc     | tailgate lid Hyundai emblem                                                                                             | \$ 83.00    |
| 13                                | 1 pc     | tailgate lid weatherstrip                                                                                               | \$ 242.00   |
| 14                                | 1 pc     | rear end panel                                                                                                          | \$ 580.00   |
| 15                                | 1 pc     | rear end panel top garnish                                                                                              | \$ 188.20   |
| Less 25 %                         |          |                                                                                                                         | \$ 3,521.10 |
|                                   |          |                                                                                                                         | \$ 880.27   |
|                                   |          |                                                                                                                         | \$ 2,640.83 |
| <u>LABOUR &amp; MISC. CHARGES</u> |          |                                                                                                                         |             |
| 01                                |          | To check electrical lighting concerned.                                                                                 | \$ 50.00    |
| 02                                |          | To reinstall of rear bumper parking sensor.                                                                             | \$ 60.00    |
| 03                                |          | To rust-proofing of the affected areas.                                                                                 | \$ 70.00    |
| 04                                |          | Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. | \$ 700.00   |
| 05                                |          | Putty and spray painting of the affected portion.                                                                       | \$ 750.00   |
|                                   |          |                                                                                                                         | \$ 1,630.00 |
| Total                             |          |                                                                                                                         | \$ 4,270.83 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized  
2/1/21  
3 days  
2/5 \$1200  
Take photo of the repair.

req: Marcus - L46

07/01/2021 COG

20  
50  
X  
550  
400

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                          |
|-------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>    |                          |
| Owner ID Type:                      | Business                 |
| Owner ID:                           | 625X                     |
| <b>Vehicle Details</b>              |                          |
| Vehicle No.:                        | SKE3158C                 |
| Vehicle to be Exported:             | No                       |
| Intended Deregistration Date:       | 07 Jan 2021              |
| Vehicle Make:                       | TOYOTA                   |
| Vehicle Model:                      | PRIUS C CVT              |
| Primary Colour:                     | Green                    |
| Manufacturing Year:                 | 2012                     |
| Engine No.:                         | 1NZ6119134               |
| Chassis No.:                        | JTDKD3B3801001512        |
| Maximum Power Output:               | 54.0 kW (72 bhp)         |
| Open Market Value:                  | \$22,923.00              |
| Original Registration Date:         | 24 Feb 2012              |
| First Registration Date:            | 24 Feb 2012              |
| Transfer Count:                     | 1                        |
| Actual ARF Paid:                    | \$13,754.00 6877         |
| <b>Intended PARF Rebate Details</b> |                          |
| PARF Eligibility:                   | Yes                      |
| PARF Eligibility Expiry Date:       | 23 Feb 2022              |
| PARF Rebate Amount:                 | \$7,564.00               |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date:                    | 23 Feb 2022              |
| COE Category:                       | A - Car (1600cc & below) |
| COE Period(Years):                  | 10                       |
| QP Paid:                            | \$52,809.00              |
| COE Rebate Amount:                  | \$5,972.00               |
| <b>Total Rebate Amount:</b>         | <b>\$13,536.00</b>       |

The information contained herein is correct as at 07 Jan 2021

OK