



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21000307/Ktd3e2	
			Date: 19/05/2021	
			Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBB 9603S
	Policy No.	Z/20/VC00/106952	Coverage (\$)	0.00
	Claim No.	20/21/21/VC00/024086	Excess (\$)	600.00
	Assign From	KENNY LIM	Assign Date	07/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi canter (M)	c.c	2977
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	FB70BBA20235	Colour	WHITE
	Odometer	-	Steering	JAMMED
	Brakes	JAMMED	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	BEARWAY	9 mm
	L/H Front Tyre	195 R15X8	BEARWAY	9 mm
	R/H Rear Tyre	195 R15X8 (D)	SUNEW	8/8 mm
	L/H Rear Tyre	195 R15X8 (D)	SUNEW	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/01/2021	Inspection Date	08/01/2021
	Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE MARKET VALUE IS S\$28,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	