



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN : JEREMY GOH		Ref: CS3/AIG20007692/Qvd3e2-1 Date: 21/01/2021 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SML 7319T	Veh. Inspected	SGS 184U
Policy No.	1900102318	Coverage (\$)	0.00
Claim No.	4970816264SG	Excess (\$)	0.00
Assign From	JEREMY GOH	Assign Date	07/01/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	AUDI A5 SPORTBACK 2.0	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WAUZZZ8T2BA088656	Colour	BLACK
Odometer	157650 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	255/35 R19	KINFOREST	6 mm
L/H Front Tyre	255/35 R19	KINFOREST	6 mm
R/H Rear Tyre	255/35 R19	KINFOREST	6 mm
L/H Rear Tyre	255/35 R19	KINFOREST	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	25/07/2020	Inspection Date	28/07/2020
Survey held at	Majesty Autoworks Pte Ltd-39 WOODLAND CLOSE #01-36		
Repairer	-		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	