



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2100477

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 22/01/2021
Reference CS3/III20011781/Gvd3e2-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 8908T
Insured Veh. SHB 4033Z
Claim No. MCT20100461/01
Policy No. MCOM0015
Accident Date 28/10/2020
Inspection Date 29/10/2020

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Less: Pre-Repair Survey Fee (Invoice.AC2007477 dated 09/11/2020)	-120.00
Subtotal	130.00
GST (7%)	9.10
Grand Total	139.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM