

EVERDAWN AUTO SERVICE

8 Kaki Bukit Ave 4 #01-02 Premier@Kaki Bukit Singapore 415875

Tel: 6487 0828

BUS. REG. NO. 52883181W GST REG NO. M90366872T

22nd December 2020

Our Ref: GBG8908T

Your Ref: SHB4033Z

India International Insurance Pte Ltd

Motor Claims Department

64 Cecil Street

#04-05 IOB Building

Singapore 049711

Dear Sirs,

ACCIDENT INVOLVING GBG8908T AND SHB4033Z ALONG UPPER SERANGOON ROAD ON 28.10.2020

We are the representative for Mech Flo Technologies Pte Ltd, whose vehicle registration number **GBG8908T** was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration **SHB4033Z**. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

Cost of repairs	\$7,415.15
Loss of rental for 07 days @\$107.00	\$ 749.00
Survey report	\$ 674.00
LTA search fee	\$ 7.45
	<u>\$8,845.60</u>

Enclosed are the supporting documents for your perusal:-

GIA

LTA search

Repair bill

Kindly let us have your payment of **\$8,845.60** in our workshop's name within the next 14 days.

Please do not hesitate to contact our Ms Tan at 9838 8224 or email motor@iaconsultingsg.com should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,

Endl.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/10/2020 11:59
Date Of Accident	28/10/2020 08:40
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG8908T
Insured/Policyholder	
Name Of Registered Owner	MECH FLO TECHNOLOGIES PTE. LTD.
Co Reg No	2XXXXX422M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-69201451

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 3.0M
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5117661154 COMP
Cover Note Number	

Driver



扫描全能王 创建

Address 18 MANDAI ESTATE #07-07 MULTI-WIDE INDUSTRIAL BUILDING
 Postcode 729910
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions AFTER RAIN
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : VELU
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY LORRY WAS STATIONARY AT THAT TIME, GIVING WAY TO A BUS. A TAXI(SHB4033Z) CAME FROM BEHIND, HIT ONTO THE REAR OF MY LORRY.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB4033Z
 Vehicle Make/Model/Colour HYUNDAI /I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
 Details Of Properties
 Vehicle Category TAXI
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage




No. Of Passenger (Including Driver)



Sketch Plan

SKETCH PLAN



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claim history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer

L-File.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vacbk@vicom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:



LETTER OF AUTHORITY

We/I, Mech Flo Technologies Pte Ltd ("the third party claimant") of UEN/NRIC No. 2XXXXX422M, owner of vehicle Reg.No GBG 8908T hereby authorize M/s Everdawn Auto Service ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use and/or survey fee ("claim") for my vehicle no. GBG 8908T that was damaged pursuant to the accident which occurred on 28/10/20 along Upper Serangoon Road involving vehicle no/s SHB4033Z ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this _____ of _____ 20____



Signed by the third party claimant

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 28 Oct 2020 / 16:35:48

Receipt Date/Time : 28 Oct 2020 / 16:35:48

Tax Invoice/Receipt

Receipt No. : ITNET-00000-201028-003067

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHB4033Z				
As at 28 Oct 2020/08:40:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHB4033Z Enquiry Fee 20201028163452899477	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
20201028163504256		Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

HUI WANG ENTERPRISE PTE LTD

BLK 5, DEFU LANE 10, # 01-576, SINGAPORE 539186
TEL: 6286 4541, 6283 0717 FAX: 6281 0647

Nº 23662

Co. Reg. No. 201426468N

噸厘，貨車出租，車輛檢查，修理，噴漆，打嗎呷等
LORRY, VAN RENTAL, VEHICLES INSPECTION, REPAIRING, SPRAY PAINTING, PANEL BEATING, INSURANCE CLAIM, ETC.

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS

I/We Mech 810 Technologies Pte Ltd

I/C No: _____

If Different From Section 1

of 18 mandai estate #07-07 8729910

Tel No: _____

hereby confirm having agreed to hire this day from Messrs Hui Wang Enterprise Pte Ltd the undermentioned NEW/USED Vehicles at the rental fees as shown below and I agree that I shall be responsible for the first payment of \$2,000.00 / \$3,000.00 for any loss and/or damaged caused to the said vehicle and I shall be responsible to pay Messrs Hui Wang Enterprise Pte Ltd the value of the vehicle in the event of the Vehicle being CONFISCATED or any loss resulting from THEFT or DESTRUCTION of the said vehicle whether or not such damage or loss is caused by negligence or by any breach by me of the terms and conditions of hire, hereinafter mentioned and printed.

Vehicle Redg. No. 車號		GBC2499S		(Diesel / Petrol)	
Section 1 Hirer's And / Or Driver's Particulars 租車者 \ 駕駛員個人記錄				日期及取車時間 Date & Time Out: 28/10/20 1.01 pm	
Name 名 Balan Radhkrani				日期及還車時間 Date & Time In: 4/11/20 12 pm	
Address 地址 18 mandai estate #07-07				天數 Days @ \$ 100 700	
Multi-Wide Indl Bldg SE. 729910				星期 Weeks @ \$	
駕駛執照 Dr/Licence No: I/C No: G6609506 T Tel No:				月 Months @ \$	
截止日期 Expiry Date		Date Of Birth		總數 Nett-Total	
Replacement Veh. Redg. No. (Diesel / Petrol)				按櫃金 Deposit	
日期及取車時間 Date & Time Out:				Refund	
日期及還車時間 Date & Time In:				Balance To Pay	
* Note: A repossession fee of S\$100.00 will be charged on repossess vehicles				Cash / Cheque	

NOTICES: ACCIDENT EXCESS: \$ 2500 22 60%
NO INSURANCE COVERAGE FOR YOUNG (BELOW 22), OLD (ABOVE 60)
AND IN EXPERIENCED DRIVERS.

請注意水櫃里的水及引擎里的黑油須每天檢查。
Please check Radiator Water & Engine Oil daily.

半途汽油不足，遺失鑰匙等，若須服務者另付額外費用。
Extra charges are required for those vehicle that run out of petrol, lost of key and etc.

Interest rate of 1.5% will be charged on overdue payments

IMPORTANT!

I / We declare that the usage of renting the above mention Vehicle are not to be used for illegal purpose, including offences in connection with thefts, uncustomed goods, drugs dealings or trafficking or smuggling.

Signature of Hirer

I/We hereby accept the terms and conditions herein and overleaf which I have read and understood or have been read over and explain to me and understood by me. I/We hereby declare that the particulars of the Hirer and licence given above are correct in every respect and that I am the holder of a valid driving licence enabling me to drive the above-mentioned vehicle and not disqualified from driving.

Remarks: _____

Signature of Hirer

承租者簽名

HUI WANG ENTERPRISE PTE LTD

BLK 5, DEFU LANE 10, #01-570 / 576, SINGAPORE 539186
TEL: 6286 4541, 6283 0717 | FAX: 6281 0647
EMAIL: Huiwang576@Gmail.com | GST No. 201426468N

TAX INVOICE

To :

Mech Flo Technologies Pte Ltd
Everdawn Auto Services

Invoice No. : 00020110
Date : 04/11/2020
Reference : RA23662
Vehicle Number :
Repair Date :

Attn : Mech Flo Technologies Pte Ltd

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
7	Rental of GBC2499S from 28/10/20 to 4/11/20	\$100.00	\$700.00
INTEREST AT THE RATE 1.5% PER MONTH WILL BE CHARGE ON OVERDUE ACCOUNTS			
Sub-Total			\$700.00
GST 7%			\$49.00
Total Payable			\$749.00

Payment Options

Please note that if you wish to make payment via Bank Transfer or Cheque, indicate the Bank, Amount Transfer & Invoice Number in the email so we are able to confirm that the funds came through. The email can be sent to Accounts@HuiWangEnterprise.com

OCBC SGD Account

Bank Name: Oversea-Chinese Banking Corporation Limited
Account Number: 689 021 566 001
Account Name: Hui Wang Enterprise Private Limited

PayNow



UEN: 201426468N

Received By _____

Issued By _____

EVERDAWN AUTO SERVICE

8 Kaki Bukit Ave 4 #01-02 Premier@Kaki Bukit Singapore 415875

Reg No.: 52883181-W GST Reg No.: M90366827T

TEL: 6487 0828 FAX: 6382 2839

INVOICE

To: Mech Flo Technologies Pte Ltd

Invoice No. : ED20008

Date : 20/11/2020

Vehicle No. : GBG8908T

No.	Description	Qty	Unit Price	Amount
1	REPAIR COST		\$ 6,930.05	\$ 6,930.05
Sub-Total				\$ 6,930.05
GST 7%				\$ 485.10
Total				\$ 7,415.15

Payment by cheque should be crossed and made payable to 'Everdawn Auto Service'

Issued By:

.....
Authorised Signature

Our reference: 20-11-9628

Date: 18/11/2020

INVOICE NO. 9628

Mech Flo Technologies Pte Ltd
c/o Everdawn Auto Service
8, Kaki Bukit Ave 4
Premier@Kaki Bukit
#01-02 Singapore 415875

Registration No. **GBG8908T**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$674.00
Total amount			<u><u>\$ 674.00</u></u>

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.



L.L. Tan (Ms)
Principal Consultant

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.laconsultingsg.com

Our reference: 20-11-9628

Date: 18/11/2020

c/o Everdawn Auto Service
8, Kaki Bukit Ave 4
Premier@Kaki Bukit

Dear Sirs

RE: Road Traffic Accident on 28/10/2020
Mech Flo Technologies Pte Ltd

In accordance with your instructions received in this office on 29/10/2020, we made arrangements to examine the vehicle on 29/10/2020 at above-mentioned address. The following data was recorded:


Vehicle details

Make	Toyota	Registration	GBG8908T
Model	Dyna	Chassis	KDY2318027636
Colour	Silver	Gearbox	Manual
Odometer	75325km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	185R15C	85% Patlas
Front right	185R15C	85% Patlas
Rear left	165R13C	Bridgestone
Rear right	165R13C	Bridgestone

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$6,930.05 and 6 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.laconsulting.sg

Our reference 20-11-9628

Date 18/11/2020

Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
List Items:				
Tail gate	1	bent	1652.80	1652.80
Tail gate lower hinge @\$45.00	4	damaged	180.00	180.00
Tail gate side hinge latch rh	1	bent	215.40	215.40
Rear end panel	1	repair.respray	547.80	0.00
Tail gate sticker " DYNA"	1	necessary	150.00	150.00
Tail lamp @\$265.20	2	damaged	530.40	530.40
Tail lamp holder c/w bracket @\$152.50	2	bent	305.00	305.00
Rear number plate holder c/w bracket @\$112.00	2	bent	224.00	224.00
Rear carriage floor panel	1	repair	4521.00	0.00
Rear cast iron cross member	1	repair	642.00	0.00
Rear number plate licensed lamp	1	damaged	61.00	61.00
Rear exhaust pipe	1	bent-in	489.80	489.80
Rear reflector lh (round)	1	missing	75.00	75.00
Sub- Total costs			9594.20	3883.40
Percentage discount : 25%			2398.55	970.85
Sub-Total costs for parts			7195.65	2912.55

Special Nett Items:

Tail gate sticker 70km/h & 6 pax @\$20.00	2	necessary	40.00	40.00
Rear U step panel	1	bent	185.00	185.00
Rear number plate	1	bent	40.00	40.00
Tail gate reflector @\$98.00	2	cracked	196.00	196.00
Tail gate aluminium checker plate (include labour)	1	bent/warped	1752.00	1752.00
Sub-Total costs for parts			2213.00	2213.00

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsultingsg.com

Our reference 20-11-9628

Date 18/11/2020

Parts Repair

*

*

*

Sub- Total costs
Total costs for parts

0.00	0.00
0.00	0.00
9408.65	5125.55

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsultingsg.com

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	20	\$ 900.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 750.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 40.00
Remove and replace rear exhaust system	\$ 45.00	2	\$ 90.00
Transfer of existing tailgate mechanism to new tailgate	\$ 45.00	1.8	\$ 2.00
Wiring and bulb checking	\$ 45.00	0.5	\$ 22.50
Total labour cost			\$ 1,804.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.


Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$5,125.55	
Part-By-Part		\$0.00	
Further discount	0%		
Recommended cost of parts		\$5,125.55	(1)
Labour Cost Calculation (See section B)		\$1,804.50	(2)
Total Repair Cost (Round off to hundred)		\$6,930.05	(1) + (2)

We would recommend a sum of **\$6,930.05** and **6** working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.


Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma. Mechanical Engineering
NTC-2 Automotive Technology
Sr.MIES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council
ACTA Certified Trainer, Singapore

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.laconsultingsg.com

