

N51
2 Kaki Bukit Ave 2, #01-17 & 18,
Singapore 417921

Insurer Reference:
Repairer Reference: 038894
Date calculated: 05/05/2021 12:26 PM

Full Report
Registration: SLZ3908H
Printed: 05/05/2021 12:26 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	N51 User01	Currency:	SGD
Claim Reference:		Date of Incident:	05/01/21
Estimated Repair Time:	3	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle		
Manufacturer:	TOYOTA	
Model:	PRIUS +	
Sub Model:	BASE MODEL	
Model Sheet Number:	70 A4 54	
Registration:	SLZ3908H	
VIN number:		
Odometer:		
Model Specs		
FROM 03.2018	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Code	Description	WU	Price SGD
190011)	DETACH + REFIT BATTERY CABLE INCLUDES: R + R BOOT STORAGE BOX AND NECESSARY ATTACHED PARTS	2.0	10.00
B410)	R + R REAR BUMPER	4.0	20.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	5.00
NO NUMBER	R + R REAR BUMPER REINFORCEMENT	2.0	10.00
743921	R + R END PANEL TRIM	2.0	10.00
NO NUMBER	R + R R/BOOT FLOOR COVER	2.0	10.00
2711	REAR PANEL REPAIR	10.0*	50.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		2.30	23.0
Total of Labour			115.00

Paint

Paint Work		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
3860	REAR BUMPER N- PART PAINT ST K1G	22.0	110.00
3790	REAR PANEL REPAIR PAINT ST III	11.0	55.00
NO NUMBER	PREPARE FOR PAINTING	21.0	105.00
NO NUMBER	PAINT PREPARATION FOR PLASTIC PARTS (COMPOSITE WORK)	8.0	40.00
Total Paint		Hrs 6.20	WU 62.0
			Price SGD 310.00

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD
3904	R/LOAD FLOOR COVER	57627 47020	Original	179.00
2620	R/R BUMPER BRACKET	52155 47010	Original	139.60
2583	REAR BUMPER	52159 47912	Original	523.90
2640	REAR BUMPER REINF	52023 02140	Original	205.70
2587	REAR BUMPER SPOILER	76891 47040	Original	325.00
f: OEM Parts				0.00
n: Non-OEM Parts				1,373.20
u: Used parts				-686.60
Savings				
Subtotal				
Subtotal Discount(+50.00%)				
Total				686.60

Extras

Code	Description	Price SGD
1000	RR Bumper Clips	30.00*
1001	RR Reverse Sensor	200.00*
1003	RR Bumper Spoiler Clips	30.00*
Total Extras		260.00

Code	Description	Price SGD
------	-------------	-----------

Final Calculation

	SGD	SGD
Parts	1,373.20	
Total Discount(+50.00%)	-686.60	
Total Parts		686.60
Labour Time Base 10 WU/h		
Total 23.0 WU X 50.00 SGD/h	115.00	
Total Of Labour		115.00
Total Of Extras		260.00
Paint Work Time Base 10 WU/h		
Labour Cost 62.0 WU X 50.00 SGD/h	310.00	
Total Paint Including Material		310.00
Repair Cost Excludes GST		1,371.60
GST (+7.0%)		96.01
Repair Cost Included GST		1,467.61

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

4/5
 1350.00