



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI21000365/Ktd3e2	
			Date: 28/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7209U	Veh. Inspected	SFY 3253P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21000036MFSH	Excess (\$)	0.00	
Assign From	SANGHILAN VIC	Assign Date	08/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi outlander (A)	c.c	2360	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JMYXTGF3WZF001971	Colour	METALLIC DARK BLUE	
Odometer	94160 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50Z R18	HANKOOK	5 mm	
L/H Front Tyre	235/50Z R18	HANKOOK	5 mm	
R/H Rear Tyre	235/50Z R18	HANKOOK	8 mm	
L/H Rear Tyre	235/50Z R18	HANKOOK	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2020	Inspection Date	08/01/2021	
Survey held at	160 SIN MING DRIVE B #08-13			
Repairer	AERO GARAGE PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	