

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBC 8529A
Vehicle Model : NISSAN NV200
Accident Date : 06.01.2021
Original Reg Date : 26.12.2013

Date : 08.01.2021
Chassis : VSKYBAM20U0062203
TP Ins. **ERGO**

ESTIMATE

1	1 pc	Tailgate RH		1,159.30
2	1 pc	Tailgate Glass RH		398.20
3	1 pc	Tailgate Windscreen Inner Seal RH		60.00
4	1 pc	Tailgate Emblem dci		69.60
5	1 pc	Tailgate Inner Bottom Lock RH		156.20
6	1 pc	Tailgate Inner Bottom Lock Catch RH		58.00
7	1 pc	Tailgate Inner Rubber RH		139.20
8	2 pcs	Tailgate Hinge RH	86.00	172.00
9	1 pc	Tailgate Checker RH		72.00
10	1 pc	Tailgate Inner Board RH		292.50
11	1 set	Tailgate Inner Board Clips RH		40.00
12	1 pc	Tailgate Weatherstrip		195.20
13	1 pc	End Panel		465.00
14	1 pc	Rear Bumper		790.00
15	2 pcs	Rear Bumper Side Retainers	39.00	78.00
16	1 set	Rear Bumper Clips		50.00
17	1 pc	Rear Bumper Sponge		119.60
18	1 pc	Rear Bumper Reflector RH		67.90
19	1 pc	Taillamp RH		289.50
20	1 pc	Tailgate Badge LH		78.20
21	1 pc	Tailgate Emblem NV200 LH		125.10

4,875.50

Less 10% 487.55

4,387.95

3760

10% 3384

C/D

4,387.95

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBC 8529A

B/F

4,387.95

Special Nett

1	1 pc	Tailgate Glass Sealant	60.00
2	1 pc	Tailgate Sticker 70km/h	15.00
3	1 set	Reverse Sensor	250.00

rec 40.
na
200mm
255

Labour charge

Panel Beating	1,000.00
Spray painting	900.00
Check Wiring	30.00
Anti rust	60.00
Remove and install tailgate glass.	120.00
Remove and install tailgate part.	90.00
Remove and install carpet and interior.	150.00
Remove and install reverse sensor	90.00

600.
600.
✓
30.
60.
60.
60.
30

7,152.95

Less 20% 1,430.59

Lump sum 5,722.36

1470

Tanpin 97495719
WP' 2/1/2019 430
05 days
1/5 Repair after repair
tanpin@1hunts.com

5109
1/5 \$4100.
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- Any illegal modification(s) is/are
- Supplementary item(s) must be submitted and approved by the company
- is subject to final approval by the company

Acknowledged by Repairer

Signature

Date