



TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

AIG

Uche  
Lealia

NOT Adm  
dln  
a/s \$7000  
5 days  
When photo taken 12/1  
8/1/21

|                |                   |
|----------------|-------------------|
| Vehicle number | SLU7523J          |
| Make / Model   | TOYOTA/WISH       |
| Chassis number | JTDGJ20W205001472 |
| Accident date  | 06 01 2021        |
| Reference      | 2101-11           |

Qty Particulars

Unit Price - SGD \$

| PARTS REPLACEMENT - LIST ITEMS |                                          |            |
|--------------------------------|------------------------------------------|------------|
| 1                              | REAR BUMPER D.S ✓                        | 566.01     |
| 2                              | REAR BUMPER SIDE BRACKET 11X             | 764.75 ✓   |
| 2                              | REAR BUMPER SIDE RETAINER 11X            | 150.92 X   |
| 2                              | REAR BUMPER DAMPER 11X                   | 139.26 X   |
| 2                              | REAR BUMPER REFLECTOR o/scre 1pc 57.78   | 281.30 X   |
| 1                              | REAR END PANEL 505.20                    | 115.56 1pc |
| 1                              | REAR END PANEL TOP GARNISH 7w. ✓         | 503.47 ✓   |
| 1                              | REAR LOWER INNER PANEL 245.50            | 182.62 ✓   |
| 1                              | FLOOR PANEL 12X                          | 589.20 ✓   |
| 1                              | FLOOR PANEL INNER GARNISH 12X            | 583.40 X   |
| 1                              | FLOOR PANEL TOP BOARD 11X                | 316.20 ✓   |
| 2                              | REAR TAILAMP o/scre 1pc 326.25           | 301.45 X   |
| 2                              | REAR TAILAMP INNER SEAL 11X              | 652.51 1pc |
| 2                              | REAR FENDER INNER TRIM o/scre 1pc 396.92 | 30.00 X    |
| 1                              | EXHAUST SILENCER 12X                     | 793.84 1pc |
| 2                              | EXHAUST MOUNTING 11X                     | 791.34 X   |
| 1                              | TAILGATE 305.00                          | 30.00 X    |
| 2                              | TAILGATE ABSORBER 11X                    | 1314.33 ✓  |
| 1                              | TAILGATE EMBLEM LOGO 11X                 | 346.43 X   |
| 1                              | TAILGATE EMBLEM 11X                      | 31.00 ✓    |
| 1                              | TAILGATE OUTER CHROME 11X                | 49.00 ✓    |
| 1                              | TAILGATE WEATHERSTRIP 11X                | 219.50 ✓   |
| 1                              | TAILGATE GLASS MOULDING 128.10           | 309.10 ✓   |
| 1                              | TAILGATE LOCK 11X                        | 180.00 ✓   |
| 1                              | TAILGATE LOCK STRIKER 11X                | 509.30 ✓   |
| 2                              | TAILGATE HINGE 11X Del/Torn 485.10       | 54.20 X    |
| 1                              | TAILGATE INNER TRIM BOARD 11X            | 131.70 X   |
| 1                              | REAR WINDSCREEN 11X                      | 680.20 ✓   |
| 2                              | REAR WINDSCREEN MOULDING 11X             | 1065.90 ✓  |
| 1                              | WIPER 11X                                | 120.00 X   |
| 1                              | WIPER MOTOR 11X                          | 42.60 X    |
| 2                              | TAILGATE LAMP 11X                        | 800.00 ✓   |
|                                |                                          | 920.69 ✓   |
|                                |                                          | 12999.77   |
|                                | Less 25%                                 | 2596.97    |
|                                | Subtotal                                 | 7790.90    |

8135.87  
25.4  
6101.50

|       |                                                     |             |          |
|-------|-----------------------------------------------------|-------------|----------|
|       |                                                     | Balance C/F | 7790.90  |
|       | <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>       |             |          |
|       |                                                     | Balance B/F | 7790.90  |
| 1 SET | REAR BUMPER CLIP <i>all</i>                         | 40.00       | ✓        |
| 1 SET | REAR FENDER INNER TRIM CLIP <i>11</i>               | 30.00       | X        |
| 1 SET | REAR REVERSE SENSOR <i>shut</i>                     | 400.00      | 200      |
| 1     | JOINT SEALANT <i>all</i>                            | 150.00      | 50       |
| 1     | WINDSCREEN SEALANT <i>all</i>                       | 150.00      | 40       |
|       | Subtotal                                            | 770.00      |          |
|       |                                                     | Balance C/F | 8560.90  |
| S/No  | <u>LABOUR AND MISCELLANEOUS CHARGES</u>             |             |          |
|       |                                                     | Balance B/F | 8560.90  |
| 1     | CHECK REAR WIRING AND LIGHTNING SYSTEM              | 60.00       | 30       |
| 2     | REMOVE, REFIT REAR LINING, TRIM AND GARNISH         | 200.00      | 80       |
| 3     | REMOVE AND RENEW REAR REVERSE SENSOR                | 120.00      | 50       |
| 4     | REMOVE AND RENEW EXHAUST ASSY                       | 150.00      | X        |
| 5     | REMOVE AND REFIT REAR WINDSCREEN                    | 120.00      | ✓        |
| 6     | TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW | 200.00      | 60       |
| 7     | PANEL BEATING ON AFFECTED AREAS                     | 1400.00     | 900      |
| 8     | SPRAY PAINTING ON AFFECTED AREAS                    | 1600.00     | 1000     |
| 9     | APPLY ANTI RUST ON AFFECTED AREAS                   | 120.00      | 80       |
|       | Subtotal                                            | 3970.00     |          |
|       |                                                     | Grand total | 12530.90 |

9009 6608

P- 6101.90

S.N- 330

L- 2320

8751.90

202

7001.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: