



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

13/1/2021

Survey Details:

Date of loss	4-Jan-21
Date of appointment	8-Jan-21
Date of survey	11-Jan-21
Location of survey	GOLD AUTOWORKS

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	SGM 2597E
Make and Model	TOYOTA ESTIMA 2.4A
Date of registration	12/10/2006
Excess	-
Market Value	\$ 8,500.00
Parf Rebate	\$ 4,256.00
Nett Loss	\$ 4,244.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	\$ -
Check items (estimate)	\$ -
Labour	\$ -
Total	\$ -
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>7</u>
---------------------------	----------



Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$6,000.00 - \$7,000.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	