

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Wednesday, 3 February 2021 9:56 AM
To: Shiau Chan (LKKAUTO)
Subject: RE: III-PAPER SURVEY SLE 5482R DONE BY GUO QIANG

Dear Shiau Chan,

AUDIT CHECK DONE FOR SLE5482R, FOUND REAR LH FENDER INNER SHIELD & BOTH DOORS OUTER HANDLES ARE RECOMMENDED TO REPLACE.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 2 February, 2021 5:35 PM
To: Simon Ho (LKKAUTO)
Subject: III-PAPER SURVEY SLE 5482R DONE BY GUO QIANG

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)