



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0003/2021/NS
DATE	:	5-Jan-21
WIP	:	65417

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR CHEONG HENG LIM
ADDRESS	:	60 WILKINSON ROAD SINGAPORE 436717
TELEPHONE	:	HP +65 93397811
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100431329-05
VEHICLE NO	:	SKV 6958 B
MODEL CODE	:	AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR	:	29/9/2015
ENGINE NO	:	CZC 267121
CHASSIS NO	:	WAUZZZ8V3G1005440
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	2-Jan-21
PLACE OF ACCIDENT	:	STADIUM BLVD ROUNDABOUT EXIT TO STADIUM DR



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 6958 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$ 350.00	280 ✓
3	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	X ✓
4	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	1000 1500
SUB TOTAL LABOUR CHARGES		: <u>\$ 3,710.00</u>	R.S.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 6958 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER AND LHS SILL PANEL. ✓ ✓	\$ 3,400.00	1100 ✓
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. ✕ ✕	S/N \$ 280.00	✕
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 7,582.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 6958 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT FENDER - LH <i>Dented.</i>	\$	841.00	✓ 672.80
2 FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$	71.00	+
3 FRONT FENDER BRACKET - LH <i>new</i>	\$	27.00	+
4 WHEEL HOUSING LINER - LH <i>new</i>	\$	167.00	+
5 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	88.00	+
6 FRONT DOOR - LH <i>new Dented</i>	\$	2,494.00	+ 1995.00
7 FRONT DOOR OUTER SEAL - LH <i>new</i>	NEC \$	159.00	+ 127.00
8 BONDING AGENT <i>new</i>	NEC \$	47.00	+
9 CLEANING SOLUTION <i>new</i>	NEC \$	65.00	+
10 FRONT DOOR ATTACHMENT PARTS <i>new</i>	\$	238.00	+
11 FRONT DOOR CATCH <i>new</i>	\$	104.00	+
12 EXTERIOR MIRROR MOUNTING - LH <i>new</i>	\$	1,013.00	+
13 MIRROR CAP - LH <i>new</i>	\$	148.00	+
14 FRONT ALUMINIUM RIM - LH <i>new</i>	\$	699.00	+
15 SUNDRIES <i>new</i>	\$	250.00	? 20.96
TOTAL SPARE PARTS	:	\$ 6,411.00	
TOTAL LABOUR CHARGES	:	\$ 7,582.00	
GRAND TOTAL	:	\$ 13,993.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *08/01/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, OS Pays*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT