



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1027/2020/NS
DATE : 30-Dec-20
WIP : 64774

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SGL 4425 K

Direct Asia Insurance(SG) Pte Ltd

88 South Bridge Road

Singapore 058716

Alig.

Attn: Motor Claims Dept

Tel: 65321818 - Fax: 6516 0904

OWNER'S NAME : MS TAN YI TING
ADDRESS : BLK 130 BEDOK RESERVOIR ROAD
#10-1353
SINGAPORE 470130
TELEPHONE : HP +65 91993737
TYPE OF CLAIM : ~~THIRD PARTY CLAIM~~ *OD claim.*
POLICY NO : 1700094139-03
VEHICLE NO : **SLV 4371 U**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 28/12/2017
ENGINE NO : CVN 045312
CHASSIS NO : WAUZZZF41JA023310
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Dec-20
PLACE OF ACCIDENT : BLK 130 BEDOK RESERVOIR ROAD OPEN CARPARK



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4371 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4371 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Dehnd</i>		\$ 2,111.00	✓
2 FRONT BUMPER FIXING PARTS <i>new</i>		\$ 282.00	+
3 FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 70.00	+
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$ 208.00	+
5 FRONT BUMPER AIR GUIDE - RH <i>new</i>		\$ 62.00	+
6 FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>		\$ 134.00	+
7 FRONT BUMPER GUIDE SECTION - RH ?		\$ 37.00	?
8 FRONT FENDER - RH <i>Dented</i>		\$ 758.00	✓
9 FRONT FENDER ATTACHMENT PARTS <i>new</i>		\$ 200.00	+
10 FRONT FENDER CLOSING ELEMENT - RH <i>new</i>		\$ 49.00	+
11 FRONT FENDER BRACKET - RH ?		\$ 35.00	?
12 DEFORMATION ELEMENT BRACKET - RH ?		\$ 49.00	?
13 FRONT FENDER BRACE - RH ?		\$ 117.00	?
14 WHEEL HOUSING LINER - RH <i>new</i>		\$ 239.00	+
15 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$ 90.00	+
16 WHEEL SPOILER - RH <i>new</i>		\$ 73.00	+
17 WHEEL SPOILER TRIM - RH <i>new</i>		\$ 36.00	+
18 STONE CHIP GUARD - RH <i>new</i>		\$ 50.00	+
19 TOP FENDER LEDGE COVER - UPPER ?		\$ 31.00	?
20 TOP FENDER LEDGE COVER - LOWER ?		\$ 23.00	?
SUB TOTAL SPARE PARTS	:	\$ 4,654.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4371 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 LED HEADLIGHT - TH <i>Abel new</i>		\$ 7,693.00	<i>+</i>
22 LIFT CYLINDER - RH <i>Abel new</i>		\$ 208.00	<i>+</i>
23 SUNDRIES <i>?</i>		\$ 250.00	<i>?</i>
TOTAL SPARE PARTS	:	\$ 12,805.00	
TOTAL LABOUR CHARGES	:	\$ 5,002.00	
GRAND TOTAL	:	\$ 17,807.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lj
08/01/21

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

are authorized, 04 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT