

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 6341B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT	658.00	500.00
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.00	-
2	REAR BUMPER BRACKET @\$114.00	SERVICEABLE	228.00	-
1	REAR BUMPER LIP	CUT	728.90	580.00
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	68.00	-
1	REAR FENDER RH	SERVICEABLE	897.00	-
1	REAR FENDER COWLING RH	SERVICEABLE	128.30	-
1	TAILLAMP RH	SERVICEABLE	587.00	-
1	REAR TAILLAMP LOWER BRACKET RH	SERVICEABLE	82.00	-
1	REAR WHEEL BEARING RH	SERVICEABLE	298.00	-
1	REAR ABSORBER RH	SERVICEABLE	387.00	-
1	AXLE	SERVICEABLE	1,598.00	-
	LESS 20% DISCOUNT		-1,154.44	-
	LESS 25% DISCOUNT		-	-270.00
			4,617.76	810.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
1	REAR WHEEL HUB COVER RH (SN)	SCRATCHED	100.00	100.00
1	SET REAR FENDER COWLING CLIPS (SN)	SERVICEABLE	50.00	-
			480.00	130.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND RENEW REVERSE SENSOR.		150.00	30.00
	REMOVE AND RENEW REAR UNDERCARRIAGE.	NOT NECESSARY	400.00	-
	CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	40.00
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	300.00

Report Ref No. CS/AGI21000462/Qtd3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS.		600.00	200.00
			2,180.00	660.00
	GRAND TOTAL		7,277.76	1,600.00

RECOMMENDED COST OF LUMP SUM REPAIRS		1,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI21000462/Qtd3q2

Ja

OI SUN PIN

**Asst. Automotive Assessor** 

X.2.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.