

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAI	L INSURANCE (S) PL	-	Ref:	CS/AGI21000462/Qtd3q2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	05/03/2021	
				Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLU 6351U	Veh. Inspected		SMW 6341B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008559/ST	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		11/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS 5DR	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	JTDKB3FU203092791	Colour		WHITE	
	Odometer	7197 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	DUNLOP		6 mm	
	L/H Front Tyre	195/65 R15	DUNLOP		6 mm	
	R/H Rear Tyre	195/65 R15	DUNLOP		6 mm	
	L/H Rear Tyre	195/65 R15	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	31/12/2020	Inspection Date	•	12/01/2021	
	Survey held at 60 JALAN LAM HUAT, #05-21					
	Repairer	MY CAR CONSULTANT PTE LTD				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: