Mechanical Inspection Report Request

Kamaliah KAMIS (SPF) < Kamaliah_KAMIS@spf.gov.sg>

Wed 16/9/2020 9:44 AM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the <u>4 vehicles</u> below: [The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS].

a. Case IAFP-IB-20200911 - Mechanical Inspection of Taxi, SHC1614L (TP/IP/28223/2020)

On the 2 July 2020 (Thursday) sometime around 6.13 a.m., the driver was driving the said taxi on lane 1 of 3-lane road along Bukit Panjang Ring Road towards the direction of Jelebu Road. In the midst of making a right turn at a signalised cross-junction of Senja Link on green signal, the taxi encroached into the travel path of a motorcycle, who was oncoming from the opposite direction. Thereafter, the motorcycle collided onto the taxi's left front portion, causing serious injuries to the rider of the motorcycle. General inspection is required to inspect if there is/are any mechanical faults to the taxi.

Vehicle to be inspected: SHC1614L - Driver (Potential Defendant)

IO In-Charge: SIO Sufiyan Khairi

b. Case IAFP-IB-20200911 - Mechanical Inspection of Motorcycle, JTY1342 (TP/IP/36851/2020)

On 28 August2020 sometime before 3.05 a.m., the Deceased was riding his motorcycle JTY1342 along Jurong Island Highway on lane 1 of 4 lanes road. On reaching near to lamp post 108, the Deceased was believed to have lost control of his motorcycle, which veered to the right and collided into the road kerb, causing the Deceased to end up on the centre divider and the motorcycle to fall onto the road. Deceased sustained multiple injuries and was pronounced dead at the scene by attending SCDF paramedic at 3.25 a.m.

<u>Vehicles to be inspected:</u> JTY1342 - Rider (Deceased)

IO In-Charge: SIO Adrian Lim

c. Case IAFP-IB-20200911 - Mechanical Inspection of Motorcycle, FBK4118L (TP/IP/37951/2020)

On 3 September 2020 sometime before 6.25 a.m., the motorcycle was traveling on lane 1 of 2 lanes of Woodlands Avenue 1 towards the direction of Woodlands Avenue 11. The pedestrian was crossing from the centre divider to the other side (from right to left in the motorcycle's perspective). As pedestrian was crossing the road (not within 50 meters of the pedestrian crossing), the pedestrian stopped in the middle of lane 1 as the pedestrian spotted the motorcycle approaching towards the motorcycle. The motorcycle did not stop in time and collided onto the pedestrian. Due to the collision, both pedestrian and motorcycle fell onto the road.

<u>Vehicles to be inspected:</u> FBK4118L - Rider (Potential Defendant)

IO In-Charge: DOC Jerry Yeo

d. Case IAFP-IB-20200911 - Mechanical Inspection of Motor Car, SLU9036K (TP/IP/21353/2020)

On the 27 April 2020 at about 1856 hrs, the motor car made a right turn from Dunlop Street into Clive Street. The driver subsequently felt an impact from the right side of his vehicles. The driver claimed the pedestrian could have fallen onto his car from the pedestrian walkway. The pedestrian was injured and conveyed conscious to the hospital. The pedestrian sustained internal head injury and subsequently passed away on 12 May 2020 at 1930 hrs.

Vehicles to be inspected: SLU9036K - Driver (Potential Defendant)

IO In-Charge: SIO Firdaus

- 2. These request has been <u>approved</u> by my management.
- 3. Thank you Sirs.
- cc: DOC Jerry, DOC Saleha & SIO Yazid, as requested by you Bryan, fyip

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team Traffic Police Department | Singapore Police Force DID: (65) 6547 6435 | FAX: (65) 6547 6352





Singapore Police Force – Commemorating 200 Years of Policing

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."