

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0023/2021/NS
DATE : 11-Jan-21
WIP : 65456

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR SOH BOON KEONG(SU WENQIANG)
ADDRESS : 7 SOON LEE STREET
#02-40
SINGAPORE 627608
TELEPHONE : HP +65 91442625
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070006564
VEHICLE NO : **SKF 5525 H**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 17/1/2020
ENGINE NO : CVK 087755
CHASSIS NO : WAUZZZF48KA117072
MILEAGE : 25670KM
DATE IN : 5-Jan-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Jan-21
PLACE OF ACCIDENT : 5 LORONG BAKAR BATU CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 5525 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	✓ TO REMOVE AND RENEW BONNET. REPAIR LHS A-PILLAR. ✓	\$ 1,400.00	750. ✓
2	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS, REMOVE AND REINSTALL BOTH WING MIRROR ASSY. S/N \$ 800.00 RENEW DAMAGED TRIMS AND WINDOW GLASSES.	280. ✓	
3	✓ TO RESPRAY BONNET, LHS A-PILLAR AND BOTH FRONT ✓ DOORS. ✓ LH only	\$ 3,200.00	1650. ✓
4	TO RENEW FRONT WINDSCREEN. S/N \$ 480.00	✓	
5	TO REMOVE AND REINSTALL BOTH FRONT SEATS FOR GLASS SHARD REMOVAL. INSPECT DASHBOARD AND CENTRE CONSOLE TRIMS FOR DAMAGES. AND RENEW IF NECESSARY. S/N \$ 1,050.00	? X	
SUB TOTAL LABOUR CHARGES		: \$ 6,930.00	

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 5525 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT INTERIOR AND EXTERIOR GROOMING INCLUSIVE OF VACUUM GLASS SPLINTERS AND CLEAN UP GLASS.	S/N \$ 500.00	✓
7	TO CARRY OUT WATER LEAKAGE TEST.	S/N \$ 150.00	✓
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
9	TO ARRANGE TOWING FROM ACCIDENT SCENE.	\$ 280.00	X
10	TO REAPPLY PAINT COATING TO AFFECTED AREA.	\$ 400.00	? 300
TOTAL LABOUR CHARGES		: \$ 8,452.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 5525 H

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 BONNET <i>2x Dented</i>	\$	2,763.00	☒ 2710.40
2 BONNET IMPACT PROTECTION - CENTRE	\$	27.00	☒ 21.52
3 BONNET IMPACT PROTECTION - LH	\$	28.00	☒ 21.84
4 BONNET IMPACT PROTECTION - RH	\$	27.00	☒ 21.52
5 PLENUM CHAMBER COVER <i>Not Nec</i>	\$	96.00	? X
6 AERO WIPER ARM - LH/RH <i>Not nec</i>	2 \$	240.00	X
7 AERO DYNAMIC WIPER BLADES SET <i>cut</i>	\$	102.00	☒ 82.40
8 WATER DEFLECTOR STRIP - LH/RH <i>cut</i>	2 \$	132.00	☒ 106.88
9 FRONT WINDSCREEN <i>Shattered</i>	\$	1,125.00	☒ 900
10 RAIN SENSOR GEL FOIL <i>nec</i>	\$	132.00	☒ 105.20
11 RETAINING SPRING <i>Not nec</i>	\$	20.00	? X
12 INTERIOR MIRROR SPRING CLIP <i>Not nec</i>	\$	21.00	? X
13 PRIMER <i>nec</i>	\$	19.00	☒ 14.96
14 A-PILLAR TRIM - LH/RH <i>cut</i>	2 \$	404.00	? 323.20
15 WINDSCREEN DEFROSTER NOZZLE GRILLE <i>Not nec</i>	\$	122.00	? X
16 WINDSCREEN DEFROSTER NOZZLE <i>Not nec</i>	\$	166.00	? X
17 DASHBOARD VENT TRIM - RH <i>Not nec</i>	\$	424.00	? X
18 DASHBOARD VENT TRIM - LH <i>Not nec</i>	\$	929.00	? X
19 DASHBOARD TRIM - LH <i>Not nec</i>	\$	687.00	? X
20 DASHBOARD TRIM - RH <i>Not nec</i>	\$	375.00	? X
SUB TOTAL SPARE PARTS	:	\$ 7,839.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 5525 H

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 CENTRE CONSOLE TRIM INSERT <i>new</i>	\$	367.00	? X
22 CENTRE CONSOLE TRIM COVER FRAME <i>new</i>	\$	566.00	? X
23 WINDOW GUIDE - LH <i>new</i>	\$	446.00	X
24 TRIM STRIP WINDOW GUIDE <i>cut</i> (2)	\$	254.00 127.20	202.80
25 CORNER TRIM - LH <i>cut</i>	\$	45.00	✓ 35.84
26 WINDOW SLOT SEAL - LH <i>new</i>	\$	303.00	X
27 WINDOW GUIDE TRIM STRIP <i>new</i>	\$	254.00	X
28 FRONT DOOR WINDOW - RH <i>new</i>	\$	286.00	X
29 FRONT WINDSCREEN SEALANT <i>new</i>	\$	200.00	✓
30 FRONT WINDSCREEN IU BRACKET <i>new</i>	\$	26.00	✓
31 SUNDRIES <i>Na.</i>	\$	300.00	? 3.20 ✓
TOTAL SPARE PARTS	:	\$	10,886.00
TOTAL LABOUR CHARGES	:	\$	8,452.00
GRAND TOTAL	:	\$	19,338.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NAME : Adnan Li
SURVEYED DATE : 11/01/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

are authorized, 08 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT