

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Preli. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

18/1/21 4/5 @ 5000 confirmed via Alu.

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

Make: Asher
not allowed
12/1/21

1/58 5000/
4 days

VEHICLE No: SMT 4163C

NETT ITEM

1PC	TAILGATE	DD	1018.20	\$1,455.00	
1PC	TAILGATE GLASS MOULDING	neu	108.50	\$188.20	
1PC	TAILGATE WIPER ARM	11		\$86.90	X
1PC	TAILGATE WIPER MOTOR	11		\$481.00	X
1PC	TAILGATE REAR LOGO	neu	64.90	\$65.00	
1PC	TAILGATE 'NOTE' EMBLEM	neu		\$62.00	
1PC	TAILGATE OUTER GARNISH	11		\$344.90	X
1PC	TAILGATE INNER LOCK	111	128.40	\$245.00	
1PC	TAILGATE INNER TRIM	De / Torn	366.20	\$388.90	
1SET	TAILGATE INNER TRIM CLIPS	neu		\$50.00	
1PC	TAILGATE WEATHERSTRIP	111	68.20	\$199.00	
1PC	TAILGATE LOCK SENSOR	Che	250.00	\$320.00	
1PC	REAR BUMPER	DD / oe	460.00	\$980.00	
1PC	REAR BUMPER SPONGE	Torn		\$122.00	
2PCS	REAR BUMPER SIDE RETAINERS @\$45.00	0/5 Bent	35.00	\$90.00	1pc
2PCS	REAR BUMPER BRACKETS @\$105.00	0/5 DD	90.80	\$210.00	1pc
1SET	REAR BUMPER CLIPS	neu		\$50.00	
1PC	REAR END PANEL	DD	552.80	\$650.00	
1PC	REAR END PANEL TOP GARNISH	111	248.50	\$455.00	
2PCS	TAILLAMPS @\$605.00	0/5 cro	325.20	\$1,210.00	1pc
2PCS	TAILLAMP HOUSING PANELS @\$305.00	R		\$610.00	X
1PC	REAR FENDER	R		\$911.00	X
1PC	REAR FENDER INNER TRIM	11		\$388.00	X
1PC	REAR FLOOR PANEL	R		\$991.00	X
1PC	REAR FLOOR PANEL TOP BOARD	11		\$650.10	X
1PC	REAR EXHAUST	R		\$520.00	X
				\$11,723.00	

(102)

S.NETT

1PC	REAR WINDSCREEN SEALANT	neu	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	neu	\$50.00	40
1PC	REAR LICENCE PLATE	11	\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR	Should	\$280.00	200
1SET	REAR REVERSE CAMERA	11	\$380.00	X
1PC	REAR END PANEL SEALANT	neu	\$50.00	X
1SET	REAR FLOOR PANEL INSULATOR	11	\$250.00	X

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	60
TO SPRAY RUST PROOFING	\$120.00	60

TO RESET & REPROGRAMME SYSTEM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$100.00	50
	\$1,800.00	800
	\$1,500.00	1100
TOTAL	\$16,853.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

40007