

FASTTECH AUTO PTE LTD  
1 KAKI BUKIT AVE 6 #01-48  
SINGAPORE 417883

Here we are

Not Authored  
12/1/21  
2/5 \$7100/

4 days

VEHICLE No: SLF 232Z

1PC	BOOTLID	R	\$2,623.00	X
2PCS	BOOTLID REFLECTORS @\$ 774.15	n	\$1,548.30	X
1PC	BOOTLID REAR LOGO	n	\$122.00	✓
1PC	BOOTLID 'A4' EMBLEM	n	\$94.20	✓
1PC	BOOTLID INNER LOCK	su	\$277.00	X
1PC	BOOTLID INNER TRIM	n	\$361.00	X
1PC	BOOTLID WEATHERSTRIP	tw	\$203.00	✓
1PC	REAR BUMPER	20/22	\$2,898.00	✓
1PC	REAR BUMPER LOWER CENTRE BLACK GRILLE	tw	\$266.90	✓
1PC	REAR BUMPER LOWER	gro	\$246.00	✓
1PC	REAR BUMPER REFLECTOR O/S	CNE	\$65.00	✓
1PC	REAR BUMPER REINFORCEMENT	3nt	\$1,402.00	✓
4PCS	REAR BUMPER PDS SENSORS @\$198.00	Should	\$792.00	1PC
1PC	REAR BUMPER TOW COVER	n	\$35.00	X
2PCS	REAR BUMPER EXHAUST CHROMES @\$350.00	0/5 3nt	\$700.00	1PC
2PCS	TAILLAMPS @\$1008.00	CNE	\$2,016.00	✓
1PC	REAR END PANEL	DS	\$857.00	✓
1PC	REAR END PANEL TOP GARNISH	su	\$164.00	X
1PC	REAR END PANEL OUTER BRACKET O/S	n	\$68.00	X
1PC	REAR FLOOR PANEL	R	\$1,280.00	X
		(52)	\$15,118.00	
	S.NETT			
1SET	REAR BUMPER CLIPS	n	\$60.00	50
1PC	REAR LICENCE PLATE	n	\$50.00	X
	TO CHECK WIRING		\$80.00	20
	TO DISMANTLE & REPLACED REAR PDC SENSOR		\$100.00	50
	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY		\$120.00	80
	TO RESET & REPROGRAMME SYSTEM		\$100.00	50
	TO TRANSFER BOOTLID MECHANISM	n	\$150.00	X
	TO SPRAY RUST PROOFING		\$150.00	30
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$1,200.00	800
	TO PUTTY & SPRAY PAINTING		\$1,500.00	800
	TOTAL		\$18,628.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7426.1  
52  
7054.79