

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21000543/Kvf3q2	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	18/02/2021	
			Code	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJE 5055P	Veh. Inspected	SHC 5568K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008554/LA	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	12/01/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS (A)	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	JTDKB3FU803092584	Colour	M.P.WHITE / RED	
	Odometer	27707 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	DUNLOP	8 mm	
	L/H Front Tyre	195/65 R15	DUNLOP	8 mm	
	R/H Rear Tyre	195/65 R15	DUNLOP	8 mm	
	L/H Rear Tyre	195/65 R15	DUNLOP	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	•	General Information			
	Accident Date	31/12/2020	Inspection Date	13/01/2021	
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD			
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.		Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: