

12.3.1

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 15-Jan-21

MODEL: HYUNDAI I40

INSURANCE: Sampo

VEHICLE NO.: SHD 3333 D (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
HEADLAMP (LH) <i>mainly work</i> 1388.00	1	\$2,776.00	\$2,776.00
SUB TOTAL			\$2,776.00
LESS 20%			\$555.20
DISCOUNTED TOTAL			\$2,220.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance			

1 yan

1110-40

2kk Auto

[Signature]