



3A Automobile Pte Ltd

Office Address : No 120 Lower Delta Road #02-15 Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

To : Sompo Insurance Singapore Pte Ltd

Vehicle Number: SLM 8784 H

Tel :

Make and Model: KIA FORTE

Fax :

Date Of Accident: 7/1/2021

Attn: Claim Department

Time Accident: 2000HRS

Unit	List Items	Unit Price	Prices
1 pc	REAR BUMPER repair <i>scr</i>	\$ 688.00	\$ 688.00
1 pc	BUMPER REFLECTOR RHS X <i>SVC</i>	\$ 95.00	\$ 95.00
8 pcs	REAR BUMPER CLIPS \$ <i>all</i>	\$ 3.00	\$ 24.00
S/Total			\$ 807.00
Less -20%			\$ (161.40)
			\$ 645.60

712
10%
640.80

	To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on the Affected Areas & Components with Oven Spray Booth Facilities	\$ 600.00	\$ 600.00
	To Remove & Replace the Damaged Parts as Listed Above, including Reinstatements of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts	\$ 400.00	\$ 400.00

200
400
200

Total

640.80
400.00

\$ 1,645.60

Regards,

Yours faithfully,

3A Automobile Pte Ltd
Person to contact : Alwin / Enjo
Mobilephone : 9786 8677 / 6738 7777

1040.80
20%
832.64
45.80
2 days

Rasul
Hp 900 10568
2 days
4/5
13/01/2021 @ 1420

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resurvey after repair
email: rasul@lkkauto.com