




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO21000601/GUvf3e2 Date: 27/01/2021 Code: SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.		SLG 3871D	Veh. Inspected		SKU 3968Y
Policy No.			Coverage (\$)		0.00
Claim No.		CMTD2100138/SYH	Excess (\$)		0.00
Assign From		GRACE TEO	Assign Date		13/01/2021
2. Vehicle Particulars & Condition					
Make & Model		HONDA MOBILIO SV 1.5	c.c		1497
Engine No.		HIDDEN	Year of Reg.		2015
Chassis No.		MRHDD4870FP000214	Colour		BLACK
Odometer		-	Steering		IN ORDER
Brakes		IN ORDER	Modification		STANDARD ALLOY RIM
General		GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
	L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
	R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm	
	L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information					
	Accident Date	12/01/2021	Inspect Date / Time 13/01/2021 ( 04:30 PM )		
	Survey held at	8 Kaki Bukit Avenue 4 #04 – 20 Premier			
	Repairer	A-TEC AUTOMOTIVE PTE LTD			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

Report Ref No. CS3/SMO21000601/GUvf3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.