

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ivy Yong

Date: 12 Apr 2021

### **Preliminary Advice**

Insured Vehicle No	: SLM5657L	Accident Date	: 12/01/2021
TP Vehicle No	: SGF7485Z	Assignment Date	: 13/01/2021
Make	: HYUNDAI AVANTE	Est. Duration of Repair	: 4
Date of Inspection	: 13/01/2021		
Inspection At	: CN MOTORS PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

#### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,670.40
Revised Amount	:S\$	2,507.63
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,507.63
Lump Sum Repair	:S\$	2,000.00

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :