



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Chai Yi Ann Louis 50 Soo Chow Drive Soo Chow Garden Singapore 575550 Contact No Mobile: 82990192	Cust No/Name /Mr Chai Yi Ann Louis Reg No/Reg Date SLV7040E / 11/01/201 Date In/Mileage / 0 Chassis No KNAFJ411MJ5757633 Engine No G4FGHH689042 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	13/01/2021/ 10:36	TLC	442 / CocoLu	27286			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E PNT88000							2400.00	
RENEW FRT BUMPER, FRT FENDER LH, FRT DOOR LH, FRT SUPPPORT PANEL							1200	
E PNT88000							X 160.00	
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS							1050.00	
E PNT98000								
SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH,							120.00	
B WHEELALIGNMENT								
To Conduct Computerize Full Wheel Alignment							30.00	
M SUNDRY								
TRANSFER FRT LEFT RIM							30.00	
A 90000001								
CHECK WIRING & ELECTRICAL SYSTEM							120.00	
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST							400.00	
A 90000001								
RENEW FRT UNDER CARRIAGE							380.00	
M SUNDRY								
SUPPLY FRT LEFT RIM							NN 40.00	
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION							20.00	
M SUNDRY								
Sundry								
M COVER-FR BUMPER	BR				1.00	633.00	00.00	633.00
M GRILLE ASSY-RADIATOR	?	X NN			1.00	160.00	00.00	160.00
M DUCT ASSY-AIR CURTAIN,LH	?	CRU			1.00	6.00	00.00	6.00
M MOULDING-FRONT BUMPER A/INTAKE	?	X NN			1.00	91.00	00.00	91.00
M COVER-BLANKING FR FOG LH	?	X NN			1.00	18.00	00.00	18.00
M AIR DUCT-FR BUMPER,LH	CRU				1.00	33.00	00.00	33.00
M BRACKET-FR BUMPER SIDE MTG,LH	BR				1.00	13.00	00.00	13.00
M LAMP ASSY-HEAD,LH	BR				1.00	810.00	00.00	810.00
M GUARD ASSY-FRONT WHEEL,LH	TNI				1.00	95.00	00.00	95.00
M CARRIER ASSY-FRONT END MODULE	?	BR			1.00	675.00	00.00	675.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Mr Chai Yi Ann Louis		Cust No/Name /Mr Chai Yi Ann Louis	
50 Soo Chow Drive		Reg No/Reg Date SLV7040E / 11/01/201	
Soo Chow Garden		Date In/Mileage / 0	
Singapore 575550		Chassis No KNAFJ411MJ5757633	
Contact No Mobile: 82990192		Engine No G4FGHH689042	
		Make/Model KIA/FORTE K3 1.6 A L 189	
		Colour/Trim BAU GRAVITY BLUE / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	13/01/2021/ 10:36	TLC	442 / Cocolu	27286

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL-FENDER,LH / 00	1.00	376.00	00.00	376.00
M INSULATOR-FENDER LH ? X NM	1.00	28.00	00.00	28.00
M PANEL ASSY-FRONT DOOR,LH / 00	1.00	1542.00	00.00	1542.00
M BLACK TAPE-FRT DOOR FRAME UPR. / ncc	1.00	13.00	00.00	13.00
M BLACK TAPE-FR DR RR,LH / ncc	1.00	12.00	00.00	12.00
M DUCT ASSY-EXTENSION ? X NM	1.00	144.00	00.00	144.00
M HUB ASSY-FR WHEEL ? X NM	1.00	150.00	00.00	150.00
M KNUCKLE-FRONT AXLE,LH ? X NM	1.00	350.00	00.00	350.00
M GEAR ASSY-STEERING ? X NM	1.00	832.00	00.00	832.00
M STRUT ASSY-FR,LH / BT	1.00	313.00	00.00	313.00
M BEARING-STRUT / ncc	1.00	54.00	00.00	54.00
M STAY LH ? X NM	1.00	23.00	00.00	23.00
M ARM COMPLETE-FR LWR,LH / BT	1.00	380.00	00.00	380.00
M CROSSMEMBER COMPL ?	1.00	1330.00	00.00	1330.00

Steve (LKK) , wk Am L
13/1/21, 12:30pm
p/p
By Bel SM
9 & days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed

Confirm & accepted by: (Signature) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nett 12,831.00
7% GST on 12831.00 898.17
Total Payable 13,729.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.