

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255249)

109, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



arrange survey
14 Jan 2021
1030am

owner in 10am
13.1.21

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 57195
Date Estimated : 13/01/2021
Prepared By : Brandon Chan Eng Meng

- ESTIMATE REPAIR FOR -

Atan Chua
6 Pari Dedap Walk
#07-02

Singapore 486060

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN5588J	WBAYH12050EM94256	29/04/2019	X2 sDrive18i	0

DESCRIPTION

To replace front bumper, front LH fender & attachment item
cause by accident.

To spray paint front bumper, front LH fender.

To replace left headlight.

To check electrical wiring system at the front section
for proper function including adjustment of headlights.

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

To carry out body cavity preservation.
(Per panel).

Sundries

VALUE

1700 2580.00

1730 1923.00

408 481.00

150 177.00

150 177.00

100 118.00

80, ? 150.00

Total Labour 1: 5,576.00

DESCRIPTION

FRT LH SIDE PANEL

FRT BUMPER TOP CARRIER

IMPACT ABSORBER TOP (M)

FRT BUMPER PANEL PRIMED (M PDC/PMA)

LH HEADLIGHT LED TECHNOLOGY

QTY

PRIC

1 667.35

1 375.85

1 60.45

1 1,288.15

1 3,086.85

VALUE

667.35

375.85

60.45

1,288.15

3,086.85

Total Parts : 5,478.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

383, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 57195
Date Estimated : 13/01/2021
Prepared By : Brandon Chan Eng Meng

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN5588J	WBAYH12050EM94256	29/04/2019	X2 sDrive18i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD	3rd Party	Uninsured losses / Direct Settlement
Regn No.		Claim No.
Date & Time	14/01/2021 @ 1125	Excess S\$
Surveyor's Name	RASUL	Sign
Surveyor's Tel	96010068	Authorised Yes / No
Authorised Date		Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No		
Surveyor's E-mail	rasul@lkkauto.com	
No. of Working Days Recommendation	5 days	

11,068.65



Labour 1	:	5,576.00
Parts	:	5,478.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	773.83
Grand Total	:	11,828.48

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **