

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 57195**  
Date Estimated : **13/01/2021**  
Prepared By : **Brandon Chan Eng Meng**

### - ESTIMATE REPAIR FOR -

**Atan Chua**  
**6 Pari Dedap Walk**  
**#07-02**

**Singapore 486060**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

| REGN. NO.       | CHASSIS NO.              | REGN. DATE        | MODEL               | MILEAGE  |
|-----------------|--------------------------|-------------------|---------------------|----------|
| <b>SKN5588J</b> | <b>WBAYH12050EM94256</b> | <b>29/04/2019</b> | <b>X2 sDrive18i</b> | <b>0</b> |

| DESCRIPTION                                                                                                                        | ORIGINAL PRICE | NETT     |
|------------------------------------------------------------------------------------------------------------------------------------|----------------|----------|
| To replace front left fender and attachment including make good the front bumper and knock out dented area caused by the accident. | 1,700.00       | 1,700.00 |
| To respray front bumper and front left fender.                                                                                     | 1,730.00       | 1,730.00 |
| To replace left LED technology headlight.                                                                                          | 408.00         | 408.00   |
| To check electrical wiring system at the front section for proper function.                                                        | 150.00         | 150.00   |
| To remove old PDC assembly to facilitate repair including conduct check for proper function.                                       | 150.00         | 150.00   |
| To carry out body cavity preservation.<br>(Per panel).                                                                             | 100.00         | 100.00   |
| Sundries                                                                                                                           | 80.00          | 80.00    |

| DESCRIPTION                 | UNIT PRICE | QTY   | NETT     |
|-----------------------------|------------|-------|----------|
| FRT LH SIDE PANEL           | 667.35     | 1.00  | 667.35   |
| # EXPANDING RIVET BLACK     | 1.40       | 10.00 | 14.00    |
| LH HEADLIGHT LED TECHNOLOGY | 3,086.85   | 1.00  | 3,086.85 |

### # SUPPLEMENTARY ITEMS

|                                 |          |
|---------------------------------|----------|
| Total Labour :                  | 4,318.00 |
| Total Parts :                   | 3,768.20 |
| Total Labour & Parts :          | 8,086.20 |
| Deduction for Excess :          | 0.00     |
| Total Repair Costs less Excess: | 8,086.20 |
| GST @7%:                        | 566.03   |
| Grand Total :                   | 8,652.23 |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 57195**  
Date Estimated : **13/01/2021**  
Prepared By : **Brandon Chan Eng Meng**

### - ESTIMATE REPAIR FOR -

**Atan Chua**  
**6 Pari Dedap Walk**  
**#07-02**

**Singapore 486060**

### - ACCOUNT - 135

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

| REGN. NO.       | CHASSIS NO.              | REGN. DATE        | MODEL               | MILEAGE  |
|-----------------|--------------------------|-------------------|---------------------|----------|
| <b>SKN5588J</b> | <b>WBAYH12050EM94256</b> | <b>29/04/2019</b> | <b>X2 sDrive18i</b> | <b>0</b> |

| DESCRIPTION | ORIGINAL PRICE | NETT |
|-------------|----------------|------|
|-------------|----------------|------|

| DESCRIPTION             | UNIT PRICE | QTY   | NETT  |
|-------------------------|------------|-------|-------|
| # EXPANDING RIVET BLACK | 1.40       | 10.00 | 14.00 |

### # SUPPLEMENTARY ITEMS

|                        |       |
|------------------------|-------|
| Total Labour :         | 0.00  |
| Total Parts :          | 14.00 |
| Total Labour & Parts : | 14.00 |