



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV15285/JULIANNA NG YEN HONG
	Reg No/Reg Date	SMR6729T / 17/01/202
	Date In/Mileage	13/01/2021/ 0
	Chassis No	MMBSTA13AKH004810
	Engine No	3A92UJK2598
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	14/01/2021/ 09:50	QUK	282 / Kevin Leong	61805				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	REPLACE FRT BUMPER, BONNET, FRT RH FENDER, SUPPORT PANEL, BODY KIT & AFFECTED AREA REPAIR ON FRT LH FENDER & FRT RH DOOR								3150.00
E PNT98000	PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, FRT RH DOOR & SUPPORT PANEL								2100.00
E PNT88000	REPLACE REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR RH TAIL LAMP PANEL, REAR RH FENDER & AFFECTED AREA								3600.00
E PNT98000	PAINT WORK ON REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR RH FENDER, REAR RH TAIL LAMP PANEL & BODY KIT								2450.00
E PNT88000	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								120.00
A 55900099	TO TOP UP AIR CON GAG								80.00
E PNT88000	REMOVE & INSTALL REAR PARKING ASSIST								120.00
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								120.00
E PNT88000	TO REMOVE & REAR SEAT FOR FACILITATE REPAIR								120.00
E PNT88000	TO TRANSFER REAR BOOT ATTACHMENT TO NEW PANEL								120.00
E PNT88000	TO REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR								240.00
M SUNDRY	TO APPLY WINDSCREEN SEALANT								80.00
M SUNDRY	TO APPLY BODY SEALANT ON AFFECTED PANEL								80.00
M SUNDRY	PERFORM RUST PREVENTION								80.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

CYCLE & CARRIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV15285/JULIANNA NG YEN HONG
	Reg No/Reg Date	SMR6729T / 17/01/202
	Date In/Mileage	13/01/2021/ 0
	Chassis No	MMBSTA13AKH004810
	Engine No	3A92UJK2598
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/01/2021/ 09:50	QUK	282 / Kevin Leong	61805

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY TO SUPPLY C & C EMBLEM				40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
A 15900099 TO REPLACE REAR EXHAUST MUFFLER				450.00
M SUNDRY SUNDRIES				50.00
M HEADLAMP ASSY,LH	1.00	660.00	23.00	508.20
M HEADLAMP ASSY,RH	1.00	660.00	23.00	508.20
M LAMP ASSY,COMB,RR RH	1.00	335.00	23.00	257.95
M LAMP ASSY,LICENSE PLATE	1.00	51.00	23.00	39.27
M TANK,WINDSHIELD WASHER	1.00	74.00	23.00	56.98
M CAP,WASHER TANK FILLER	1.00	7.00	23.00	5.39
M HORN	1.00	79.00	23.00	60.83
M PIPE,EXHAUST TAIL	1.00	603.00	23.00	464.31
M SEAL RING,EXHAUST PIPE	1.00	8.00	23.00	6.16
M HANGER,EXHAUST MUFFLER	1.00	22.00	23.00	16.94
M FACE,FR BUMPER	1.00	703.00	23.00	541.31
M COVER,HEADLAMP SUPT PANEL	1.00	62.00	23.00	47.74
M MARK,THREE-DIA	1.00	69.00	23.00	53.13
M BRACKET,FR BUMPER,RH	1.00	13.00	23.00	10.01
M BRACKET,FR BUMPER,LH	1.00	13.00	23.00	10.01
M AIR DAM,SIDE,FR RH	1.00	18.00	23.00	13.86
M AIR DAM,SIDE,FR LH	1.00	18.00	23.00	13.86
M GRILLE,FR UNDER	1.00	165.00	23.00	127.05
M GARNISH,FR BUMPER,RH	1.00	127.00	23.00	97.79
M BRACKET,RR BUMPER,LH	1.00	28.00	23.00	21.56

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV15285/JULIANNA NG YEN HONG
	Reg No/Reg Date	SMR6729T / 17/01/202
	Date In/Mileage	13/01/2021/ 0
	Chassis No	MMBSTA13AKH004810
	Engine No	3A92UJK2598
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/01/2021/ 09:50	QUK	282 / Kevin Leong	61805

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET,RR BUMPER,RH	1.00	28.00	23.00	21.56
M FACE,RR BUMPER	1.00	748.00	23.00	575.96
M GRILLE,RADIATOR	1.00	554.00	23.00	426.58
M HOOD	1.00	734.00	23.00	565.18
M INSULATOR,HOOD	1.00	177.00	23.00	136.29
M HINGE,HOOD,LH	1.00	56.00	23.00	43.12
M HINGE,HOOD,RH	1.00	56.00	23.00	43.12
M DAM,HOOD	1.00	20.00	23.00	15.40
M LATCH,HOOD	1.00	69.00	23.00	53.13
M FENDER,FR RH	1.00	497.00	23.00	382.69
M FENDER,FR LH	1.00	497.00	23.00	382.69
M PANEL ASSY,FR END	1.00	1055.00	23.00	812.35
M PANEL,HEADLAMP SUPPORT,UPR	1.00	65.00	23.00	50.05
M PANEL,QTR,OTR RH	1.00	763.00	23.00	587.51
M PANEL,RR COMB LAMP HSG,RH	1.00	60.00	23.00	46.20
M REINF,RR PILLAR,RH	1.00	126.00	23.00	97.02
M FLOOR,RR	1.00	956.00	23.00	736.12
M PANEL,RR END	1.00	425.00	23.00	327.25
M GLASS,RR WINDOW	1.00	544.00	23.00	418.88
M STOPPER,WINDSHIELD GLASS	2.00	3.00	23.00	4.62
P SPACER,RR WINDOW	2.00	9.00	23.00	13.86
M WEATHERSTRIP,TRUNK LID	1.00	157.00	23.00	120.89
M PANEL,TRUNK LID	1.00	791.00	23.00	609.07
M HINGE,TRUNK LID,LH	1.00	203.00	23.00	156.31
M HINGE,TRUNK LID,RH	1.00	203.00	23.00	156.31
M LATCH,TRUNK LID	1.00	218.00	23.00	167.86
M SHIELD,FR WHEELHOUSE,RH	1.00	98.00	23.00	75.46
M GARNISH,RR END PANEL	1.00	336.00	23.00	258.72
M MARK,THREE-DIA	1.00	69.00	23.00	53.13
M MARK,ATTRAGE	1.00	21.00	23.00	16.17
M TRIM,RR END	1.00	66.00	23.00	50.82
M BOARD,TRUNK ROOM FLOOR	1.00	195.00	23.00	150.15
M UNPAINTED BODYKITS	1.00	1643.00	20.00	1314.40

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV15285/JULIANNA NG YEN HONG
	Reg No/Reg Date	SMR6729T / 17/01/202
	Date In/Mileage	13/01/2021/ 0
	Chassis No	MMBSTA13AKH004810
	Engine No	3A92UJK2598
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/01/2021/ 09:50	QUK	282 / Kevin Leong	61805

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EMBLEM ECO	1.00	17.00	00.00	17.00

Estimate

Confirm &amp; accepted by

	Nett	24,946.42
7% GST on	24946.42	1746.25
<b>Total Payable</b>		<b>26,692.67</b>

\_\_\_\_\_  
Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.