



18 FEB 2021

Your Ref

Our Ref

: TP/11667/FBR4361M/YP1918R

BY FAX & HAND

India International Insurance Pte Ltd 64 Cecil Street #04-00 & #05-00 IOB Building Singapore 049711

ATTN: Motor Claims Dept

Dear Sir/Madam,

Accident Involving FBR4361M & YP1918R on 10/01/2021

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

TOTAL	\$2	<u>,853.45</u>
3. LTA Vehicle Insurance Search Fee	\$	7.45
2. Loss of Use (4 days x \$20)	\$	80.00
1. Cost of Repair (Inc 7% GST)	\$2	,766.00

We attached our Tax Invoice, Authorisation To Act, Discharge Voucher and LTA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan

Manager/Insurance Dept





AUTHORISATION TO ACT



I, Ban Hook thin co. Pte Utd	(the third party claima	nt) of 6 Deful	ane 4
Subapore 539410	(address), owner of	FBR4361M	(vehicle no.)
hereby authorize ban tock this co	. He ita	("the workshop")	to act for me
with respect to my claim for repair costs a	and/or rental and/or loss	of use ("claim")	for my vehicle
no. FBR436IM that was damaged pur	suant to the accident v	which occurred on	10(1(2021
(date) along Carpark of Buk 809	Woodlandi ST 81 (lo	cation) involving	vehicle no/s
YP 1918R ("the accident").			

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this _____ (day) of _____ (month) 20____ (year)

Signed by "the third party claimant"

(with chop if applicable)

Signed by "the workshop"

(with chop)



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST. Reg. No. M2-0078806-X 64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 049711

Office (65) 63476100 Email insure@iii.com.sg Fax (65) 62244174 Website www.iii.com.sg

EXPRESS SETTLEMENT

<u>DISCHARGE VOUCHER</u> III-Direct Settlement (PODS)

India Ref:MFL2021D0000151 Claimant Ref:FBR 4361M

We/I, BAN HOC	K HIN CO PTE LTD ("the workshop") her	reby confirm that	we/I have reached an agreement
with the appointed	Surveyor of India International Insu	urance Pte Ltd		sultants Pte Ltd (name
of Surveyor) with r	espect to the amount claimed to	for s\$_2,750.00	(GLOBAL S	of (loss)
wee/rental), Cf	(search fee), vehicle no.FBI	R 4361M that was	damaged pursuar	nt to the accident which occurred
on _10/01/2021	(date) at 809 Woodlands Street 81		(location) involvi	ng vehicle no. YP 1918R (insured
vehicle). This is purs	uant to the inspection conducted on _	14/01/2021 (date	e) at "the workshop"	
We/I confirm that v	ve/I are/am authorized by the ow	ner BAN HOCK H	IN CO PTE LTD	("the third party
claimant") of vehicl	e no.FBR 4361M to make the claim	as set out in the a	bove paragraph ar	nd we/I have full authority to settle
the matter on his/h	er behalf in a manner that we/I o	deem fit. We/I enclo	ose herein the lett	er of authority given by "the third
party claimant".				
We/I further confirm	n that we/I will indemnify India Int	ernational Insurance	e Pte Ltd for all da	amages, loss and/or expense that
they will or have a	already incurred in the event that	"the third party cl	aimant" after the	above said agreement lodges a
	st the former for any loss and ex			repairs and/or rental and/or loss
of use pursuant to	the damage to FBR 4361M (vehicle	e no.) as a result o	f the accident.	
	the agreement reached above is			
	sident and that further this settlem	ent is reached on a	a without prejudice	and without admission of liability
basis.				
TI				
	subject to the application of Singap	ore law and the Si	ngapore Courts ha	ve exclusive jurisdiction over any
dispute arising out o	rtne same.			
VA/- //		750.00 . DAN		O DIE LID
	uto pay the total amount of S\$ <u>2,</u>	730.00 to BAIN	I HOCK HIN C	SPIELID
Dated this 29th	ay of20	21		
Dated this d	ay 0120	HIN CO		
CLAIMANT:		ST TO	MITHEOC:	((LKK))
CLAIMANT:	34		WITNESS:	cks
Signature:	0		Signature:	Signature sixta 10
	Signed by "the workshop" (with cho	op)		Signed by appointed Surveyor
Name:	um cece trang		Name:	LKK Auto Consultants Pte Ltd
NRIC:	51438367C		NRIC:	199607198R
Address:	6 Dépulaire 4		Address:	51 Ubi Avenue 1
, (44, 555)	Conservate Man	0	Address.	#01-25 Paya Ubi Ind. Park S(408933)
	Companyor Soft			
Nationality:	mgaporean		Nationality:	
Occupation:	Director		Occupation:	





Customer:

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET #04-00 & #06-00 **IOB BUILDING** SINGAPORE 049711

MOTOR CLAIMS DEPT

CLAIM NO.

: 11667

POLICY NO.

: MC/00824357

VEHICLE NO.

: FBR4361M

MAKE/MODEL

: YAM / NMAX155 ABS

TAX INVOICE

GST Reg No.: M2-0010542-7

Invoice No.

: LECR20038829-I11667

Invoice Date : 09/02/2021

Payment Due Date : 11/03/2021

(Page 1 of 3)

	4				(. 0.30 . 0. 0)
S/N	Description	<u>Action</u>	Qty	Unit Price	<u>Amount</u>
1	BAR HANDLE	REPLACE	1	\$32.00	\$28.80
				Disc %: 10%	
2	BEARING STEERING CONE UPPER	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
3	LABOUR	Supply/Install	1	\$350.00	\$350.00
4	TRANSPORT CHARGES		1	\$35.00	\$35.00
5	BELLY PAN	REPLACE	1	\$33.00	\$29.70
				Disc %: 10%	
6	CAMERA (V SYS) M6 (NON-WIFI VERSION) (NEW)	REPLACE	1	\$308.00	\$277.20
				Disc %: 10%	
7	COVER FRONT UPPER(GREY)	REPLACE	1	\$35.00	\$31.50
	,			Disc %: 10%	
8	COVER SIDE CENTRE LH (GREY)	REPLACE	1	\$21.00	\$18.90
Ü	0012.10.22 022 2 (01.2)			Disc %: 10%	
9	COVER SIDE CENTRE RH (GREY)	REPLACE	1		\$18.90
U	OOVER OBE OF THE PART (OR E.T.)			Disc %: 10%	
10	COVER SIDE LH (MATTE BLACK)	REPLACE	1		\$34.20
10	OOVER OBE EN (WINTED EN COTY)			Disc %: 10%	
11	EMBLEM (YAMAHA) LOGO	REPLACE	1		\$12.60
	LINDELIN (17 NAVI 11 IV) 2000	1121 27102	·	Disc %: 10%	
12	EMBLEM ABS	REPLACE	2		\$7.20
12	EMBEEM ABO	1121 27102	_	Disc %: 10%	******
13	FORK FRONT ASSY	REPLACE	1		\$666.00
13	TORKTRONT ASST	THE ETTOL		Disc %: 10%	4000.00
14	FRONT COWLING LH (GREY)	REPLACE	1		\$28.80
14	PRONT COVILING LIT (GRET)	INEI ENOE	•	Disc %: 10%	Ψ20.00
15	FRONT COWLING RH (GREY)	REPLACE	1		\$28.80
15	PRONT COWLING KH (GKLT)	NEILAGE	,1.	Disc %: 10%	Ψ20.00
16	LIEADI AMD ACCV	REPLACE	1		\$269.10
16	HEADLAMP ASSY	NEFLAGE		Disc %: 10%	Ψ200.10
47	HODN	REPLACE	1		\$25.20
17	HORN	NEFLAGE	1	Disc %: 10%	
				DISC 70. 1070	^

S/N	<u>Description</u>	<u>Action</u>	Qty Unit Price Amou	
18	LAMP SIGNAL FRONT LH	REPLACE	1 \$34.00 \$30.60)
19	LAMP SIGNAL FRONT RH	REPLACE	Disc %: 10% 1 \$34.00 \$30.60	O
10	ENVIRON CIGIVAL PROPERTY.	1121 27102	Disc %: 10%	
20	LEVER BRAKE LH	REPLACE	1 \$18.00 \$16.20	C
			Disc %: 10%	_
21	MIRROR RH	REPLACE	1 \$35.00 \$31.50 Disc %: 10%	J
22	MUDGUARD FRONT (GREY)	REPLACE	1 \$45.00 \$40.50	0
			Disc %: 10%	
23	PANEL 1 (MATTE BLACK) LH	REPLACE	1 \$21.00 \$18.90	C
			Disc %: 10%	_
24	PANEL METER	REPLACE	1 \$16.00 \$14.40	J
25	RACE BALL 1	REPLACE	Disc %: 10% 1 \$12.00 \$10.80	n
25	RACE BALL I	REFLACE	Disc %: 10%	J
26	RACE BALL 2	REPLACE	1 \$12.00 \$10.80	0
			Disc %: 10%	
27	RETAINER BALL BEARING	REPLACE	1 \$12.00 \$10.80	0
			Disc %: 10%	_
28	RIVET	REPLACE	5 \$1.50 \$6.78	5
29	SCREW (VISOR)	REPLACE	Disc %: 10% 4 \$3.00 \$10.80	Λ
29	SCINEW (VISON)	KLILAGE	Disc %: 10%	5
30	SPEEDOMETER ASSY	REPLACE	1 \$198.00 \$178.20	0
			Disc %: 10%	
31	STAY FRONT HEADLAMP	REPLACE	1 \$90.00 \$81.00	0
		5-51.46-	Disc %: 10%	_
32	STAY HORN	REPLACE	1 \$32.00 \$28.80 Disc %: 10%	IJ
33	WINDSHIELD	REPLACE	1 \$56.00 \$50.40	n
33	WINDSHILLD	KELLAGE	Disc %: 10%	0
34	WIRE HARNESS ASSY	REPLACE	1 \$70.00 \$63.00	0
			Disc %: 10%	
35	COVER BAR HANDLE LOWER	Replace	1 \$20.00 \$18.00	0
		D	Disc %: 10%	_
36	COVER METER GREY	Replace	1 \$7.00 \$6.30 Disc %: 10%	U
37	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD	Replace	1 \$16.00 \$14.4	0
01	OTIONER (MODORNEDO) OIDEOOVER WINDOTTELED	Поріаво	Disc %: 10%	•
38	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Replace	1 \$14.00 \$12.6	0
			Disc %: 10%	







S/N	Description	<u>Action</u>	Qty	Unit Price	<u>Amount</u>
		SUB TOTAL			\$2,585.05
		GST @ 7 %			\$180.95
		GRAND TOTAL (SGD)	1	,	\$2,766.00
Validi	tv: 30 days				

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Printed by: RAYMOND





Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time :

13 Jan 2021 / 16:35:53

Receipt Date/Time:

13 Jan 2021 / 16:35:52

Tax Invoice/Receipt

Receipt No.: ITNET-00000-210113-002866

Previous Receipt No.:

1 Tevious (Toosipi Tto) :				
S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - YP1918R As at 10 Jan 2021/12:00:00 Insurance Co: INDIA INT'L INS PTE LTD 1 Insurance Enquiry - YP1918R				
Enquiry Fee 20210113163310411042		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20210113163444246	Direct Debit: eN Internet Ba		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

3/30/2021 Merimen e-Claims

View Received Message

This mail is associated with:

*FBR4361M (MFL2021D0000151) [YP1918R]

TP BAN HOCK HIN CO PTE LTD Jan 10 2021 12:00PM Ban Hock Hin Co. Pte Ltd

Reply	Reply All Mark as Unread Print Message Delete Message Forward
From	India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/03/2021 11:13 AM.
То	LKK_HQ
Subject	Alert - Adj Mandate Approved (\$\$2853.45) - FBR4361M - Claim Handler: Derrick Tan Ming Chye

Approved:2853.45:Dear Sir, please proceed with direct settlement. Thank you.

DOCUMENTS SUMMARY

There are no documents.