

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21000690/Gvf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date:	22/04/2021	
			Code	: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLN 8821D	Veh. Inspected	SMQ 6728B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008671/ST	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	14/01/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ACCENT 1.4	c.c	1368	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	KMHCU41BTKU444627	Colour	RED	
	Odometer	23384 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	175/70 R14	KUMHO	6 mm	
	L/H Front Tyre	175/70 R14	KUMHO	6 mm	
	R/H Rear Tyre	175/70 R14	KUMHO	6 mm	
	L/H Rear Tyre	175/70 R14	KUMHO	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	13/01/2021	Inspection Date	15/01/2021	
	Survey held at	eld at HUAT HOCK MOTOR WORKSHOP			
		BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: