

A.S. REC. BY:

REF:

C031M62000712/AT13

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2700477043Claims No. 694873788886 300

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05888 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE6831K Yr Regn: 2016 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Andi AB C.C. 1385Colour: White A/C: Insured / Std / NI / NASp. Reading: 68639 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ28VXG1105177Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R/16R: 205/55 R/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 06 mm / R/Bal. 06 mmL/Bal. 06 mm / L/Bal. 06 mmD.O.A. _____ D.O.I. 13/01/21Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD A16</u>
	<u>\$5364.16 5 days</u>
	<u>Red: 3920.84 (42%)</u>
	<u>MV: 68K</u>
	<u>PV: 422K</u>
	<u>Nett</u>

Date/Time, File Pass to?



: Preli. Report

Days Of Repair: 5

Resurvey No. of Trip: _____

1)



: Final Report

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.H. / C

5364.16



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0033/2021/NS
DATE	:	12-Jan-21
WIP	:	10873

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR CHONG TZE EE
ADDRESS	:	BLK 558 HOUGANG ST 51 #08-388 SINGAPORE 530558
TELEPHONE	:	HP +65 98282331
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2700477043-04
VEHICLE NO	:	SLE 6831 K
MODEL CODE	:	AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR	:	28/7/2016
ENGINE NO	:	CZC 564569
CHASSIS NO	:	WAUZZZ8VXG1105177
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	9-Jan-21
PLACE OF ACCIDENT	:	IKEA TAMPINES LEVEL 1 CARPARK


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 6831 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	280 ✓
2	TO DISMANTLE AND RENEW LHS FRONT DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,400.00	500 ✓
3	TO RESPRAY LHS FRONT AND REAR DOOR, LHS SILL PANEL, DOOR HANDLE AND LHS WING MIRROR COVER.	\$ 3,300.00	1650 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,242.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 6831 K

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT DOOR - LH <i>Dented</i>		\$	3,039.00	✓ 2431.20
2	FRONT DOOR OUTER SEAL - LH <i>New</i>	NEC	\$	161.00	✓ 128.40
3	BONDING AGENT <i>Not nec</i>	NEC	\$	49.00	? X
4	CLEANING SOLUTION <i>Not nec</i>	NEC	\$	68.00	? X
5	FRONT DOOR ATTACHMENT PARTS <i>New</i>		\$	241.00	+ X
6	FRONT DOOR CATCH <i>Not nec</i>		\$	105.00	? X
7	STONE CHIP <i>New</i>	S/N	\$	180.00	✓ 180
8	SUNDRIES <i>New</i>		\$	200.00	? 2.50
TOTAL SPARE PARTS		:	\$	4,043.00	
TOTAL LABOUR CHARGES		:	\$	5,242.00	
GRAND TOTAL		:	\$	9,285.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lj
SURVEYED DATE : 13/01/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 05 Dgs

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0033/2021/NS
DATE	:	12-Jan-21
WIP	:	10873

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Hi Adrian

5 days - ok - jfb - 1

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR CHONG TZE EE
ADDRESS	:	BLK 558 HOUGANG ST 51 #08-388 SINGAPORE 530558
TELEPHONE	:	HP +65 98282331
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2700477043-04
VEHICLE NO	:	SLE 6831 K
MODEL CODE	:	AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR	:	28/7/2016
ENGINE NO	:	CZC 564569
CHASSIS NO	:	WAUZZZ8VXG1105177
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	9-Jan-21
PLACE OF ACCIDENT	:	IKEA TAMPINES LEVEL 1 CARPARK

PREMIUM AUTOMOBILES



100, LEBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLE 6831 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	\$ 280.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,400.00	\$ 500.00
3	TO RESPRAY LHS FRONT AND REAR DOOR, LHS SILL PANEL, DOOR HANDLE AND LHS WING MIRROR COVER.	\$ 3,300.00	\$ 1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 5,242.00	\$ 2,622.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLE 6831 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT DOOR - LH		\$ 3,039.00	\$ 2,431.20
2	FRONT DOOR OUTER SEAL - LH	NEC	\$ 161.00	\$ 128.40
3	BONDING AGENT	NEC	\$ 49.00	
4	CLEANING SOLUTION	NEC	\$ 68.00	
5	FRONT DOOR ATTACHMENT PARTS		\$ 241.00	
6	FRONT DOOR CATCH		\$ 105.00	
7	STONE CHIP	S/N	\$ 180.00	\$ 180.00
8	SUNDRIES		\$ 200.00	\$ 2.56
TOTAL SPARE PARTS		:	\$ 4,043.00	\$ 2,742.16
TOTAL LABOUR CHARGES		:	\$ 5,242.00	\$ 2,622.00
GRAND TOTAL		:	\$ 9,285.00	\$ 5,364.16

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-10.02/21