

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9456T**AAD2101-052***Not Notified**Recovery B4 paint**88046.90*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

12 JAN 2021**SHD9456T**

JTDKB3FU003082406

TOYOTA

PRIUS

09/01/2021

TOKIO

01/08/2019

PART

- 1 COVER, FRONT BUMPER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 UNIT, HEADLAMP, LH
- 1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1
- 1 PANEL SUB-ASSY, FRONT DOOR, LH
- 1 HANDLE ASSY, FRONT DOOR OUTSIDE, LH
- 1 WEATHERSTRIP, FRONT DOOR, LH
- 1 HINGE ASSY, FRONT DOOR, LOWER LH
- 1 HINGE ASSY, FRONT DOOR, UPPER LH
- 1 TAPE, BLACK OUT, NO.1 FRT LH
- 1 TAPE, BLACK OUT, NO.2 FRT LH
- 1 TAPE, BLACK OUT, NO.3 FRT LH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH
- 1 PANEL SUB-ASSY, REAR DOOR, LH
- 1 HINGE ASSY, REAR DOOR, LOWER LH
- 1 HINGE ASSY, REAR DOOR, UPPER LH
- 1 TAPE, BLACK OUT, NO.1 REAR LH
- 1 TAPE, BLACK OUT, NO.2 REAR LH
- 1 TAPE, BLACK OUT, NO.3 REAR LH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR LH
- 1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 EMBLEM, SIDE PANEL
- 1 LINER, FRONT FENDER, LH
- 1 PANEL SUB-ASSY, QUARTER, LH

LIST	
<i>Bul/W</i>	
\$	516.00 ✓
\$	<i>Sn</i> 116.50 X
\$	<i>Sn</i> 1,781.10 X
\$	<i>Sn</i> 960.50 X
\$	<i>R</i> 1,300.70 ✓
\$	<i>Sn</i> 390.60 X
\$	<i>Sn</i> 231.30 X
\$	<i>R</i> 110.60 X
\$	<i>R</i> 97.50 X
\$	<i>na</i> 13.30 —
\$	<i>na</i> 43.50 —
\$	<i>na</i> 26.30 —
\$	<i>Sn</i> 926.00 X
\$	<i>Sn</i> 238.30 X
\$	<i>R</i> 1,294.90 ✓
\$	<i>R</i> 87.10 ✓
\$	<i>R</i> 98.90 X
\$	<i>na</i> 21.90 X
\$	<i>na</i> 34.90 X
\$	<i>na</i> 15.40 X
\$	<i>R</i> 926.00 —
\$	<i>Sn</i> 206.70 —
\$	<i>R</i> 977.80 X
\$	<i>na</i> 54.60 X
\$	<i>Sn</i> 202.50 X
\$	<i>R</i> 871.50 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2101-052**SHD9456T**

1 LINER, REAR WHEEL HOUSE, LH	\$	<i>R</i>	139.80	X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$	<i>nd/di/s</i>	594.80	✓
1 REINFORCE SUB-ASSY, ROCKER, OUTER LH	\$	<i>R</i>	583.40	X
1 REINFORCEMENT SUB-ASSY, ROCKER PANEL, LH	\$	<i>R</i>	343.40	X
TOTAL	\$		13,205.80	
25%	\$		3,301.45	
	\$		9,904.35	

Special Nett

1 FENDER CLIP	\$	<i>na</i>	65.00	X
1 FENDER LINDER CLIP	\$	<i>na</i>	65.00	✓
1 FRT BUMPER CLIP	\$	<i>na</i>	65.00	✓
1SET DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	65.00	X
1 FRT DOOR STICKER	\$	<i>na</i>	100.00	<i>60in</i>
1 TYRE	\$	<i>200SN</i>	<i>350.00</i>	<i>802in</i>
1 RIM <i>1555.50 → 258</i>	\$	<i>na</i>	1,879.40	✓
1 RIM COVER	\$	<i>na</i>	400.00	X
1SET CLIP, ROCKER PANEL MOULDING	\$	<i>na</i>	65.00	X
TOTAL	\$		3,054.40	

TOTAL PARTS \$ 12,958.75**LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 *100d*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *90d*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *110d*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *90d*

8000.00
1232
2400.00

Trans-cab Auto Services Pte Ltd

AAD2101-052

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9456T

To Check Electrical Lighting Concerned.

	\$	170.00
TOTAL	\$	3,590.00

Over All Total	\$	16,548.75
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days

20 days

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: