

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 21 Jan 2021

**Preliminary Advice**

|                    |                                                                                |                         |              |
|--------------------|--------------------------------------------------------------------------------|-------------------------|--------------|
| Vehicle No         | : SME95X                                                                       | Accident Date           | : 12/01/2021 |
| Make               | : AUDI A3                                                                      | Policy No.              | : 1800009264 |
| Assignment Date    | : 15/01/2021                                                                   | Excess                  | : S\$0.00    |
| Date of Inspection | : 14/01/2021                                                                   | Est. Duration of Repair | : 22         |
| Inspection At      | : 24 BENOI SECTOR<br>SINGAPORE 629857<br>REPAIRER: PREMIUM AUTOMOBILES PTE LTD |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |                                                                    |
|-----------------------------|------|--------------------------------------------------------------------|
| Repairer's Estimate (Gross) | :S\$ | (ESTIMATE \$83,578.00 +<br>95,537.00 SUPPLEMENTARY<br>\$11,959.00) |
| Revised Amount              | :S\$ | (INCLUSIVE OF<br>68,858.00 SUPPLEMENTARY & CHECK<br>ITEMS)         |
| Check Items (Estimated)     | :S\$ | 11,561.00                                                          |
| Total                       | :S\$ | 80,419.00                                                          |
| Lump Sum Repair             | :S\$ |                                                                    |

**Total Loss Consideration**

|                                        |      |            |
|----------------------------------------|------|------------|
| New for Old Value                      | :S\$ | 136,460.00 |
| Pre-Accident Value                     | :S\$ | 82,000.00  |
| COE / PARF Rebate                      | :S\$ | 45,957.00  |
| Salvage Value                          | :S\$ |            |
| Margin for Repair (New for Old Value)  | :S\$ | 90,503.00  |
| Margin for Repair (Pre-Accident Value) | :S\$ | 36,043.00  |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. (Based on Margin for Repair (New for Old Value))
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ABLE TO REPAIR THE VEHICLE NOT MORE THAN \$90,000.00 ON PART BY PART BASIS.