

⏪ Reply all   ⏹   🗑 Delete   🚫 Junk   🚫 Block   ⋮

**RE: SNM21D200247/C02/SLW4634G/TANKL / FW: ACCIDENT INVOLVING SMT7556H AND SLW4634G ALONG TELOK BLANGAH ST 31 ON 14 JAN 2021.**

TL

Tan Kah Leong &lt;KahLeong.Tan@sg.cntaiping.com&gt;

Fri 15/1/2021 11:38 AM

To: alfred\_ng@juseq.com.sg; assignments

Cc: Claims Dept of CTI &lt;claimsdept@sg.cntaiping.com&gt;; SUR



SMT7556H-KA.pdf

4 MB

**WITHOUT PREJUDICE  
SAVE AS TO COSTS**

Dear Alfred,

We refer to your email of below.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

**NOTICE :**

In response to the escalating Covid-19 cases, please refrain from sending hardcopy documents to us as delay is to be expected for handling hardcopy documents. All correspondence should be made via email [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com) or fax at [6224 7175](tel:62247175). Any inconvenience caused is much regretted.

Regards

**Tan Kah Leong**

Assistant Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 7175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)