



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC20012672/Qqf3e2-1 Date: 28/01/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 539T	Veh. Inspected	SGJ 6072S	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023908	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	15/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC 1.8L	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JHMF16306S210640	Colour	SILVER	
Odometer	138962 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/11/2020	Inspection Date	18/11/2020	
Survey held at	60 Jalan Lam Huat #07-06 Carros Centre			
Repairer	SEAH MOTOR TRADING CO.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	