



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21000746/Qtd3n2	Date: 26/03/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMC 8618Y	Veh. Inspected	SMN 1323J
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10008710/KY	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	15/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS 1.5 E	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MR2B23F3801181454	Colour	SILVER
	Odometer	90510 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	DUNLOP	6 mm
	L/H Front Tyre	185/60 R15	DUNLOP	6 mm
	R/H Rear Tyre	185/60 R15	DUNLOP	6 mm
	L/H Rear Tyre	185/60 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/01/2021	Inspection Date	15/01/2021
	Survey held at	60 JALAN LAM HUAT, #05-21		
	Repairer	MY CAR CONSULTANT PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	