

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0040/2021/NS  
DATE : 13-Jan-21  
WIP : 11262

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

*Hi Adrian*

*3 days - ok - jb - 1*

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MR FAHAD KHOWAJA  
ADDRESS : BLK 176A EDGEFIELD PLAINS  
#05-150  
SINGAPORE 821176  
TELEPHONE : HP +65 90681670  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2070178446  
VEHICLE NO : **SMX 1511 E**  
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC  
MODEL YEAR : 29/12/2020  
ENGINE NO : DEM 027422  
CHASSIS NO : WAUZZZF44MN004571  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 11-Jan-21  
PLACE OF ACCIDENT : TPE EXIT 9 SLIP ROAD

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 1511 E**

| <b>S/N</b>                  | <b>NATURE OF JOBS</b>                                                                                        | <b>ESTIMATED CHARGES</b> | <b>SURVEYOR'S RECOMMENDATIONS</b> |
|-----------------------------|--------------------------------------------------------------------------------------------------------------|--------------------------|-----------------------------------|
| 1                           | TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE. | S/N \$ 360.00 \$         | <b>360.00</b>                     |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.    | \$ 1,050.00 \$           | <b>500.00</b>                     |
| 3                           | TO RESPRAY REAR BUMPER.                                                                                      | \$ 900.00 \$             | <b>550.00</b>                     |
| 4                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                               | S/N \$ 192.00 \$         | <b>192.00</b>                     |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                              | <b>: \$ 2,502.00 \$</b>  | <b>1,602.00</b>                   |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 1511 E**

| S/N                         | PARTS DESCRIPTION                     | QTY | DAMAGED PARTS & PRICES |                 | REMARKS            |
|-----------------------------|---------------------------------------|-----|------------------------|-----------------|--------------------|
|                             |                                       |     | S/NETT                 |                 |                    |
| 1                           | REAR BUMPER                           |     | \$                     | 2,342.00        | \$ <b>1,873.60</b> |
| 2                           | REAR BUMPER FIXING PARTS              |     | \$                     | 166.00          |                    |
| 3                           | REAR BUMPER SECURING STRIP - UPPER    |     | \$                     | 112.00          | \$ <b>89.60</b>    |
| 4                           | REAR BUMPER SECURING STRIP - LOWER    |     | \$                     | 223.00          | \$ <b>178.00</b>   |
| 5                           | REAR BUMPER SPOILER                   |     | \$                     | 249.00          | \$ <b>198.80</b>   |
| 6                           | REAR BUMPER BRACKET - LH/RH           | 2   | \$                     | 408.00          |                    |
| 7                           | REAR LIGHT REFLECTOR - LH/RH OUTER    | 2   | \$                     | 86.00           |                    |
| 8                           | REAR LIGHT REFLECTOR - LH/RH INNER    | 2   | \$                     | 86.00           |                    |
| 9                           | REAR BUMPER CARRIER                   |     | \$                     | 1,063.00        |                    |
| 10                          | REAR BUMPER CARRIER SEAL              | 2   | \$                     | 28.00           |                    |
| 11                          | REAR BUMPER GUIDE SECTION - LH/RH     | 2   | \$                     | 46.00           | \$ <b>17.68</b>    |
| 12                          | REAR BUMPER HOLDING STRAP -LH/RH      | 2   | \$                     | 166.00          |                    |
| 13                          | REAR PARKING AID SENSOR - INNER/OUTER | 2   | \$                     | 484.00          |                    |
| 14                          | REAR PARKING AID SEAL RING            | 4   | \$                     | 14.00           |                    |
| 15                          | EXHAUST TAIL PIPE TRIM - LH/RH        | 2   | \$                     | 708.00          |                    |
| 16                          | SUNDRIES                              |     | \$                     | 250.00          |                    |
| <b>TOTAL SPARE PARTS</b>    |                                       | :   | \$                     | <b>6,431.00</b> | \$ <b>2,357.68</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                       | :   | \$                     | <b>2,502.00</b> | \$ <b>1,602.00</b> |
| <b>GRAND TOTAL</b>          |                                       | :   | \$                     | <b>8,933.00</b> | \$ <b>3,959.68</b> |

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-15/03/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF  
THE AFFECTED VEHICLE. SHOULD WE REQUIRE  
FURTHER LAOUR CHARGES AND SPARE PARTS IN THE  
PROGRESS OF REPAIR, WE SHALL INFORM YOU  
ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT